

Vehicle Estimate

Supplier: _____

Attention to: LKK

Page: 1/2

Vehicle No.:

SJR 3225K.

DETAIL LAB	
Person-in-charge:	
Chassis No.:	
Year:	

Make & Model:

1. Noah
Hybrid.

	Parts/Description	Qty	Unit Price (\$)
1	Tail Gate Assy / Bmc	1PC	1930.00
2	Tail Gate Chrome License Plate Garnish. X	1PC	420.00
3	wiper Arm Assy X	1PC	235.00
4	wiper Motor Assy. X	1PC	365.00
5	Tail Gate Inner cover / DL	1PC	615.00
6	Tail Gate Inner Handle / DL	1PC	75.00
7	Door Lock Assy. / BT	1PC	495.00
8	Tail Gate Gas struts X	2PCS	245 X 2
9	RH Tail Lamp Assy. X	1PC	565.00
10	Tail Gate Boot seal /	1PC	398.00
11	RH Bumper Cover X	1PC	325.00
12	Rear Bumper Assy / DL	1PC	685.00
13	LH / RH Reflector X	2PCS	115 X 2
14	Rr Bumper Retainer X ?	2PCS	75 X 2
15	Tow Hook Cover X	1PC	85 X 1
16	Reverse Lamps (1 Pair) X	1SET	365.00
17	End Panel Garnish (top) / DL	1PC	185.00
18	End Panel Assy. / BT	1PC	865.00
19	Rear Boot Inner cover set LH X	1PC	1350.00
20	Rear Boot Inner cover set RH. X	1PC	1850.00
21	Spare tyre Board X	1PC	1185.00
22	Floor Panel Assy X Hyper	1PC	1385.00
23	Boot Lock Striker Unit X	1PC	135.00
24	3rd seat row sliding Mechanism X	1PC	-
25	3rd seat Row Floor Panel X	1PC	1135.00
26	Tail Gate glass moulding /	1PC	325.00
27	Tail Gate Hinges X	2PCS	285 X 2
28	Rear antenna sensor	1PC	265.00
29	LH / RH Fender Inner trim Baric	2PCS	685 X 2
30	Rear Bumper Retainers	2PCS	75 X 2
31	End Panel Bracket	1PC	115 X 1
32	spare tyre panel carpet	1PC	385 X 1
33			
34			
35			
36			

Vehicle Estimate

Supplier: _____
Attention to: _____

Page: 2/2

Vehicle No.:

SGR 3225K

DETAIL LAB	
Person-in-charge:	
Chassis No.:	
Year:	

Make & Model:

T. Noah

Hybrid

Parts/Description	Qty	Unit Price (\$)
1 S/Nett.		
2 REVERSE sensor set /	1 set	400.00
3 REVERSE camera set X	1 set	400.00
4 "Hybrid" emblem /	1 pc	85.00
5 Number plate set X	1 set	60.00
6 Tail Gate clips & Fasteners /	1 set	80.00
7 Endpanel clips / Fasteners /	1 set	80.00
8 in-car camera set Front/REAR X	1 set	480.00
9 "Toyota" emblem /	1 pc	85.00
10 w/screen sealant /	2 units	80.00
11 R bumper clips /	1 set	80.00
12 Joint sealant /	1 pc	60.00
13 LH/RH Fender inner trim Board clip & fasteners	2 sets	160.00
14		
15		
16		
17		
18 LABOUR		
19 R/WINDSCREEN transfer	120	180.00
20 Panel Beating Affected Areas	600	900.00
21 Replacement Endpanel		480.00
22 Panel Repair Floor Panels		400.00
23 Transfer Tail Gate & nec items	60	120.00
24 Check wiring / diagnostics	30	120.00
25 REMOVE / Renew REVERSE sensor set	40	80.00
26 REMOVE / Renew / Refit inner trim & seats/garnish	60	120.00
27 spray painting Affected Areas	600	900.00
28 Paint Protection coating		880.00
29		
30 5 Days		
31 P/P before paint photos		
32		
33 Gno Qiang - 82880282		
34		
35		
36 19/5/21		