

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	1	Ref:	CS3/LPC21005988/T1qce2	
	300 BEACH ROAD		1	Date:	27/05/2021	
	#17-04/07 THE CO	NCOURSESINGAPORE 199555		Code:	LDC2	
1.		Deliev Dertievlere				
1.	Insured Veh.	Policy Particulars :- (THIRD PARTY CLA eh. YM 6876K Veh. Inspected			SMT 9696Z	
		TIVI 007 OK			0.00	
	Policy No.	24/24/24/1/000/024570	Coverage (\$)		0.00	
	Claim No.	21/21/21/VC00/024578	Excess (\$)			
	Assign From	GERALD POH	Assign Date		19/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	WDD2040452A585821	Colour		GREY	
	Odometer	139639 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/40 R18	PIRELLI		6 mm	
	L/H Front Tyre	235/40 R18	PIRELLI		6 mm	
	R/H Rear Tyre	235/40 R18	PIRELLI		6 mm	
	L/H Rear Tyre	235/40 R18	PIRELLI		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	18/05/2021	Inspect Date / T	ime	19/05/2021 (02:00 PM)	
	Survey held at	GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21005988/T1qce2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ **Automotive Assessor**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.