



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a Mitsubishi Outlander 2.0 2WD CVT Elegance.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: KAX00008, Credit, 18/05/2021/ 19:01, QUE, 261 / Edwin Caina, 11119

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like 'REPLACE FRT BUMPER, BONNET, FRT LH FENDER & BODY KIT' and 'SPRAY PAINT WORK ON FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, RHF DOOR, LHF DOOR, FRT SUPPORT, BODYKIT & AFFECTED AREAS'. Includes handwritten notes like '2.5 x 450' and '6 x 350'. A large 'Estimate' watermark is overlaid on the table.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



GST Reg No : MR-8500111-X

Co Reg No : 197701469G

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ng Chin Hung	Reg No/Reg Date SLX729M / 15/03/201
	Date In/Mileage 18/05/2021/ 40761	Chassis No GF7W0401264
	Engine No 4J11XP1912	Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE
	Colour/Trim D01 COSMIC BLUE / BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	18/05/2021/ 19:01	QUE	261 / Edwin Caina	11119				
Description of Goods / Services						1.00	68.00	23.00	52.36
M	HINGE, HOOD, RH					1.00	76.00	23.00	58.52
M	LATCH, HOOD	X NM				1.00	572.00	23.00	440.44
M	GRILLE ASSY, RADIATOR	BR				1.00	50.00	23.00	38.50
M	COVER, HEADLAMP SUPT PANEL	X NM				12.00	3.00	23.00	27.72
M	CLIP, RR BUMPER	MC				1.00	25.00	23.00	19.25
M	COVER, FR BUMPER	X NM				1.00	13.00	23.00	10.01
M	BRACKET, RADIATOR GRILLE, LH	X NM				1.00	863.00	23.00	664.51
M	FACE, FR BUMPER	BR				1.00	18.00	23.00	13.86
M	BRACKET, FR BUMPER SIDE, LH	X NM				1.00	428.00	23.00	659.12
M	EXTENSION, FR BUMPER	X NM				1.00	75.00	23.00	57.75
M	GARNISH, FR BUMPER, LH	(fy bp)				1.00	75.00	23.00	57.75
M	GARNISH, FR BUMPER, RH	(fy bp)				1.00	2.00	23.00	13.86
M	CLIP, ENG ROOM COVER	MC				1.00	112.00	23.00	172.48
M	GARNISH, FR BUMPER SIDE	BR (LH)				1.00	112.00	23.00	172.48
M	GARNISH, FR BUMPER SIDE	(RH) X NM				1.00	220.00	23.00	338.80
M	GARNISH, FR BUMPER SIDE	BR (LH)				1.00	220.00	23.00	338.80
M	GARNISH, FR BUMPER SIDE	(RH) X NM				1.00	48.00	23.00	73.92
M	GARNISH, FR BUMPER SIDE	BR (LH)				1.00	48.00	23.00	73.92
M	GARNISH, FR BUMPER SIDE	(RH) X NM				1.00	295.00	23.00	227.15
M	COVER, FR BUMPER (Black)	BR				2.00	6.00	23.00	9.24
M	BRKT, FR BUMPER SIDE, LWR LH	X NM				1.00	505.00	23.00	388.85
M	REINFORCEMENT, FR BUMPER	BT				1.00	135.00	23.00	103.95
M	REINFORCEMENT, FR BUMPER	BT				1.00	60.00	23.00	46.20
M	REINF, FR BUMPER SIDE, LH	BT				1.00	130.00	23.00	100.10
M	BAR, FR BUMPER GUARD	X NM				1.00	68.00	23.00	52.36
M	HINGE, HOOD, RH	X NM				2.00	2.00	23.00	3.08
M	CLIP, ENG ROOM COVER	X NM				1.00	2135.00	23.00	1643.95
M	HEADLAMP ASSY, LH	BR				1.00	350.00	23.00	269.50
M	LAMP ASSY, FOG, FR LH	BR				1.00	173.00	23.00	133.21
M	GARNISH, FR DECK	BR				1.00	19.00	23.00	14.63
M	COVER, FR DECK, LH	X NM				1.00	19.00	23.00	14.63
M	COVER, FR DECK, RH	X NM				1.00	58.00	23.00	44.66
M	PNL, HEADLAMP SUPT, UPR LH	BT							

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ng Chin Hung Reg No/Reg Date SLX729M / 15/03/201 Date In/Mileage 18/05/2021/ 40761 Chassis No GF7W0401264 Engine No 4J11XP1912 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	18/05/2021/ 19:01	QUE	261 / Edwin Caina	11119				
Description of Goods / Services									
M	PANEL, HEADLAMP SUPPORT, UPR		X NIM			1.00	230.00	23.00	177.10
M	PANEL, HEADLAMP SUPPORT, LWR		X NIM			1.00	107.00	23.00	82.39
M	TANK ASSY, RADIATOR COND		X NIM			1.00	103.00	23.00	79.31
M	AERO KIT - OUTLANDER	GR				1.00	1554.00	00.00	1554.00
M	LLC 4L	NR				1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME : Steve (LKK) 19/5/21, 5:00pm
 SURVEYOR SIGNATURE : OO-NM ML
 DATE : _____
 REMARKS : EXPERI - ?
PIP
My ReL S/L
12 days

Confirm & accepted by _____ LKK Auto Consultants hence notify Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary part(s) must be resurveyed and approved by Insurance Company Authorized signatory and company stamp	7% GST on	17327.98	17,327.98
		Nett	1212.96
	Total Payable		18,540.94

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.