

LEE SHENG AUTO PTE LTD

Kaki Bukit Ave 6, Autobay@KakiBukit

01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Acc Reg. No. : 201000701R Buss. Reg. No. : 201000701R

essrs. TAN KER HAN
A WAN THO AVENUE
347608

Attention : Motor Claim Department
Contact : 92744072

Estimate : ES001462

Date : 05/06/2021

Vehicle Num. : SLE 7546C

Make/Model : AUDI A3 SB 1.4

Chassis/Eng# :

Accident Date : 12/05/2021

Claim No. :

Reference :

Policy No. :

TPALG

Xiao Tony

Quantity	Particular	Unit Price	Amount S\$
1 PC	LIST ITEMS :		
1 PC	FRONT BUMPER <i>Dehnd</i>		1,650.00 ✓
1 PC	FRONT BUMPER REINFORCEMENT <i>Dehnd</i>		680.00 ✓
2 PCS	FRONT BUMPER RETAINER <i>Dehnd</i>		136.00 ✓
1 PC	GRILLE <i>crushed</i>	3375	850.00 ✓
1 PC	GRILLE EMBLEM <i>new</i>		195.00 ✓
1 PC	SUPPORT ASSY, HOOD <i>new</i>	3037.50	680.00 ✓
1 PC	REAR BUMPER <i>Repair</i>		1,550.00 ✓
1 PC	REAR END PANEL <i>Repair</i>		560.00 ✓
	List Total S\$:		6,301.00
	10.00% Discount S\$:		630.10
			5,670.90
	LABOUR :		
	KNOCKING, CUTTING, JACKING WELDING ETC	1000	1,500.00 <i>500</i>
	SPRAY PAINTING ON AFFECTED AREA		1,500.00 <i>500</i>
	Labour Total S\$:		3,000.00
	Total S\$:		8,670.90

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 4037.50

1/5: 3.2k.

04 Days.