

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Re	ef:	CS/CTI21006049/R1uc	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Da	ate:	21/05/2021	
			Co	ode:	СТІ	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBF 1244B	Veh. Inspected		SDG 8111B	
	Policy No.	DMCVSNW00124352000	Coverage (\$)		0.00	
	Claim No.	SNM21D202722/C02/THAMYL	Excess (\$)		0.00	
	Assign From	PAULINE THAM	Assign Date		21/05/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5. General Information						
	Accident Date	05/05/2021	Inspection Date		31/05/2021	
	Survey held at	15 FAN YONG ROAD SINGAPORE 629792				
	Repairer	MOVA AUTOMOTIVE PTE LTD				
5a.	. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						