

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

TP 1st Cap.
Ashes.

Vehicle Number : PC8973J

Date : 02.06.2021

Vehicle Model : HIACE HIGH ROOF

Chassis : GDH223200190

Accident Date : 14.05.2021/2110

TP Ins. FIRST CAPITAL

Original Reg Date : 26.03.2013

ESTIMATE (List price)

1	1 pc	Rear Roof side panel		1,856.90	+
2	1 pc	Rear Window glass		895.60	+
3	1 pc	Rear Window glass seal		158.30	+
TOTAL				2,910.80	

Labour charge

Panel Beating		1,000.00	100
To remove and install rear window glass		150.00	+
Spray painting		1,000.00	300
		\$ 5,060.80	

Person Incharge: JOHN

Direct Contact: 98287487

Email: ktmotorwerk@hotmail.com

02/06/21
Admin
02 Days. P/P.

Total: 400 (P/P)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: