

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6515 6888 / 9847 8613(HELPLINE)
EMAIL : enquiry@ricardo.com.sg WEBSITE: http://www.ricardo.com.sg



QUOTATION

M/S : YEOW TIAN SENG JEFFREY

7 MARYMOUNT TERRACE #15-06
SINGAPORE 573963

NO: WQT0801163
DATE: 20 May 2021
A/C CODE: C016816

YOUR REF: SMZ1535B
VEH REG NO: SMZ1535B
MAKE/MODEL: MERCEDES BEN E 250
SALESMAN: *2 days*

PAGE:1

| Description | Quantity | Unit Price | % | Amount |
|--|--------------------|------------|---|-----------------------|
| | | S\$ | | S\$ |
| WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE. DOA: 14/05/2021 @1755 HRS ACCIDENT INVOLVING: SMZ1535B & SKT1933R & FBG3505E CLAIM TYPE: 3RD PARTY CLAIM AGAINST SKT1933R (INSURED WITH AIG ASIA PACIFIC INS) | | | | |
| 1 REAR BUMPER | <i>Buclom</i> 1 PC | 1,716.12 | | 1,716.12 ✓ |
| 2 REAR BUMPER SIDE MOULDING LH & RH | 2 PC | 138.83 | | <i>me</i> 277.66 ✓ |
| 3 REAR BUMPER CENTRE MOULDING | 1 PC | 186.85 | | <i>me</i> 186.85 ✓ |
| 4 REAR BUMPER REINFORCEMENT | 1 PC | 922.37 | | 922.37 ✓ |
| 5 REAR BUMPER SIDE RETAINER LH & RH | <i>108</i> 2 PC | 43.16 | | <i>me</i> 86.32 X |
| 6 REAR BUMPER CLIPS | 1 LOT | 30.00 | | <i>me</i> 30.00 ✓ |
| 7 TO TUFF COAT REPAIRED AREA | 1 SVC | 60.00 | | <i>me</i> 60.00 X |
| 8 TO CUT, WELD & STRAIGHTEN REAR PORTION OF CAR CAUSED BY ACCIDENT, ADJUST & REPLACE DAMAGE PARTS. | 1 SVC | 500.00 | | 500.00 <i>2500</i> |
| 9 TO SPRAY PAINT ON REPAIRED AREAS | 1 SVC | 500.00 | | 500.00 <i>2500</i> |
| 10 TO CODING & PROGRAMMING REAR BUMPER SENSOR SYSTEM. | 1 SVC | 180.00 | | 180.00 7 |

Total S\$ 4,459.32
Add GST @ 7% 312.15
Grand Total S\$ 4,771.47

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED SEVENTY ONE AND CENTS FORTY SEVEN ONLY

YEOW TIAN SENG JEFFREY

CONFIRMED & ACCEPTED BY

LIK AIG CONSULTANTS INCORPORATED
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation For RICARDO AUTO CENTRE PTE LTD
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE