



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01,SGX CENTRE 2 SINGAPORE 068807		Ref: CS3/MSG21004587/Gtf3-1 Date: 24/05/2021 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	WC 6103J	Veh. Inspected	GBD 3594M
Policy No.	1001379622	Coverage (\$)	0.00
Claim No.	255453	Excess (\$)	0.00
Assign From	JOWYN TAY MEI LING	Assign Date	24/05/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/03/2021	Inspection Date	24/05/2021
Survey held at	24 SUNGEI KADUT ST 4, 729050 Sungei Kadut		
Repairer	LYS ENGINEERING		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			