



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21006074/T1tf3n2 Date: 27/04/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SML 4912A	Veh. Inspected	SMK 5052E
Policy No.		Coverage (\$)	0.00
Claim No.	C10010282/JM	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	24/05/2021
2. Vehicle Particulars & Condition			
Make & Model	BMW 428I GRAN COUPE	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA4A52080GA69342	Colour	BLACK
Odometer	98054 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	265/30 R19	FALKEN	6 mm
L/H Front Tyre	265/30 R19	FALKEN	6 mm
R/H Rear Tyre	265/30 R19	FALKEN	6 mm
L/H Rear Tyre	265/30 R19	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/05/2021	Inspection Date	24/05/2021
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	