

SIN BOON MOTOR CO
10 ADMIRALTY STREET,
#01-10/11, NORTHLINK BUILDING,
SINGAPORE 757695
TEL: 6257 8404, FAX: 6755 6214

DATE: 20/05/2021

FR7889R - KAWASAKI EX400R
VEHICLE REPAIR QUOTATION

LINK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date:

1	1 PC TOP WINDSHIELD	— Cut	\$275.00
2	1 PC L/H MIRROR	— Cut	\$225.00
3	1 PC R/H MIRROR	— Cut	\$225.00
4	1 PC TOP COWLING	— BR	\$975.00
5	1 PC L/H SIGNAL FENDER FRONT	— Cut	\$80.00
6	1 PC L/H SIDE FENDER UPPER	— Cut	\$630.00
7	1 PC L/H LOW COWLING	— Cut	\$340.00
8	1 PC HEADLIGHT (LED)	— CAA BT	\$2,410.00
9	LAMPSTAY (BRACKET)	— BT	\$478.00
10	R/H SIGNAL FENDER	— Re	\$82.00
11	R/H SIDE FENDER REAR	— X repair	\$215.00
12	R/H LOWER COWLING	— Re	\$328.00
13	R/H HANDLE BAR	— BT	\$242.00
14	L/H FORK ?		\$1,440.00
15	R/H FORK ?		\$1,440.00
16	FORK LOWER BRACKET	?	\$605.00
17	FORK UPPER BRACKET	?	\$595.00
18	FUEL TANK (PETROL)	— DD	\$1,920.00
19	L/H TAIL FENDER	— Cut	\$156.00
20	R/H TAIL FENDER	— Cut	\$156.00
21	EXHAUST PROTECTOR (MUFFLER)	— CAA	\$456.00
22	FRONT FENDER (MAGUARD)	— CAA	\$380.00
23	L/H FRAME SLIDER	— Cut	\$80.00
24	R/H FRAME SLIDER	— Cut	\$80.00
25	L/H HANDLE BAR END PLUG	— Cut	\$80.00
26	FRONT RIM SHAFT	?	\$153.00
27	L/H FOOT REST FRONT	X	\$136.00
28	STEERING CONE BEARING	— MC	\$210.00

\$14,392.00

LESS 10% \$1,439.20

\$12,952.80

29	FRONT NUMBER PLATE	— MC	NETT	\$20.00
30	LABOUR		NETT	\$600.00
31	TOW		NETT	\$60.00
				\$13,632.80
				GST 7% \$954.30
				\$14,587.10

4 Days
Lumpsum repair
After repair photos.
Guo Qiang - 82880282
Guo Qiang@lkauto.com
24/5/21

10
350
50