

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01,SGX CENTRE 2 SINGAPORE 068807		Ref: CS/MSG21006096/f3 Date: 24/05/2021 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FV 5195B	Veh. Inspected	SLP 3272K
Policy No.	MSD/VMT/20-417226-C	Coverage (\$)	0.00
Claim No.	MSC/V/21-000258	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIN B MADI)	Assign Date	24/05/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/05/2021	Inspection Date	24/05/2021
Survey held at	176 Sin Ming Drive, #03-09		
Repairer	BIFROST AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

02.07.2021 11.19am Speak to Mr Yee, he say owner withdraw claim.

02.07.2021 11.40am Dear Ashik, Please be informed that according to the repairer, owner already withdraw the claim.

We will close this file at our end without billing. No survey was done for this vehicle. - Summer.

Celine 15.07.2021