

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	F	Ref:	CS/CTI21006110/Uvc	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	С	Date:	24/05/2021	
			C	Code:	CTI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBM 5095B	Veh. Inspected		SKP 7288B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM21D202482/C02/SKP7288 B/TOHHS	Excess (\$)		0.00	
	Assign From	ALFRED TOH	Assign Date		24/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No. Colour					
	Odometer	Steering				
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description of Damages				
5.	General Information					
	Accident Date	28/04/2021	Inspection Date		24/05/2021	
	Survey held at	BAN HOCK HIN CO.PTE LTD				
		NO 6 DEFU LANE 4 SINGAPORE 539410				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					