

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref: CS3/GAI21006115/R1vf3		
3 TEMASEK AVENUE		Date: 25/05/2021		
#16-01 CENTENNIAL TOWER				
SINGAPORE 039190		Code: GAI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YN 4117B	Veh. Inspected	GBC 6209L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000004011	Excess (\$)	0.00	
Assign From	SHERY WONG	Assign Date	25/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/05/2021	Inspection Date	27/05/2021	
Survey held at	CARPORT AUTO SERVICE BLK 3 PIONEER ROAD NORTH #01-24 SINGAPORE 628457			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				