

TO :
ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO. : **SHD173T**

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : **TAN KOK ANN**

CONTACT : **91479663**

ADDRESS :

LICENSE NO. **SLV6632D** TRANS. :

CHASSIS NO :

MAKE / MODEL : **HONDA SHUTTLE**

ENGINE NO :

OWNER'S INSURER : **DIRECT ASIA**

JOB-CODE : **TP** S/A : **MICHELLE**

ACCIDENT DATE : **23-May-21**

SUPPLEMENTARY ITEMS

1 REAR FENDER INNER TRIM RH

QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR	REV. PRICE
<i>my cm/Di</i> 1.00	301.00	20.00	240.80	Y	

SPECIAL NETT ITEM

1 REVERSE CAMERA

1.00	680.00	0.00	680.00	Y	
------	--------	------	--------	---	--

EXCESS : : S\$ _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : ____/____/____

SURVEY BY : _____

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

Not Authorised
C/LRP 857501
Running After Rain
5 days

TO :
ATTN : MOTOR CLAIM DEPT. T/P VEH. NO. : SHD173T

ESTIMATE REPORT 1st QUOTATION

JOB NO. :

OWNER'S PARTICULAR

NAME : TAN KOK ANN

CONTACT : 91479663

ADDRESS :

LICENSE NO. SLV6632D TRANS. :

CHASSIS NO. :

MAKE / MODEL : HONDA SHUTTLE

ENGINE NO. :

OWNER'S INSURER : DIRECT ASIA

JOB-CODE : TP S/A : MICHELLE

ACCIDENT DATE : 23-May-21

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR	REV. PRICE
1	REAR BUMPER	1.00	1530.00	20.00	1224.00	Y	✓
2	REAR BUMPER SPONGE LH	1.00	66.00	20.00	52.80	Y	✓
3	REAR BUMPER SPONGE RH	1.00	66.00	20.00	52.80	Y	✓
4	REAR BUMPER BEAM	1.00	298.00	20.00	238.40	Y	✓
5	REAR BUMPER BRACKET LH	1.00	48.90	20.00	39.12	Y	✓
6	REAR BUMPER BRACKET RH	1.00	48.90	20.00	39.12	Y	✓
7	REAR BUMPER SIDE RETAINER LH	1.00	45.00	20.00	36.00	Y	✓
8	REAR BUMPER SIDE RETAINER RH	1.00	45.00	20.00	36.00	Y	✓
9	REAR BUMPER TOWING COVER	1.00	80.00	20.00	64.00	Y	✓
10	REAR BUMPER REFLECTOR LH	1.00	238.00	20.00	190.40	Y	✓
11	REAR BUMPER REFLECTOR RH	1.00	238.00	20.00	190.40	Y	✓
12	TAILGATE	1.00	1864.00	20.00	1491.20	Y	✓
13	TAILGATE HINGE LH	1.00	89.50	20.00	71.60	Y	✓
14	TAILGATE HINGE RH	1.00	89.50	20.00	71.60	Y	✓
15	TAILGATE DAMPER LH	1.00	168.00	20.00	134.40	Y	✓
16	TAILGATE DAMPER RH	1.00	168.00	20.00	134.40	Y	✓
17	TAILGATE OUTER GARNISH	1.00	426.70	20.00	341.36	Y	✓
18	TAILGATE LOCK	1.00	176.00	20.00	140.80	Y	✓
19	TAILGATE INNER BOARD	1.00	480.00	20.00	384.00	Y	✓
20	TAILGATE REFLECTOR LH	1.00	698.00	20.00	558.40	Y	✓
21	TAILGATE REFLECTOR RH	1.00	698.00	20.00	558.40	Y	✓
22	TAILGATE LOCK CATCH	1.00	58.00	20.00	46.40	Y	✓
23	TAILGATE RUBBER BEADING	1.00	197.00	20.00	157.60	Y	✓
24	TAILGATE WIPER MOTOR	1.00	485.00	20.00	388.00	Y	✓
25	TAILGATE EMBLEM (SHUTTLE)	1.00	55.80	20.00	44.64	Y	✓
26	TAILGATE LOGO	1.00	50.80	20.00	40.64	Y	✓
27	TOOLS HOUSING RH	1.00	218.00	20.00	174.40	Y	✓
28	TOOLS COVER TOP RUBBER MAT	1.00	238.40	20.00	190.72	Y	✓

29	TOOLS COVER HOUSING		1.00	Sn	428.00	20.00	342.40	Y	X
30	TOOLS COVER HOUSING LH SIDE		1.00	Ln	218.00	20.00	174.40	Y	X
31	REAR END PANEL	631-50	B1	1.00		20.00	728.00	Y	✓
32	SPARE TYRE PANEL		1.00	N	1198.60	20.00	958.88	Y	X
33	REAR END INNER MEMBER PANEL		1.00	N	870.60	20.00	696.48	Y	X
34	REAR END PANEL TOP GARNISH		1.00	N	187.00	20.00	149.60	Y	✓
35	REAR SPARETYRE INNER BOARD		CM	1.00	390.00	20.00	312.00	Y	✓
36	TAILLAMP LH		1.00	Sn	896.00	20.00	716.80	Y	X
38	TAILLAMP INNER PANEL LH		1.00	N	194.60	20.00	155.68	Y	X
39	REAR FENDER INNER SHIELD LH		1.00	Sn	103.00	20.00	82.40	Y	X
40	REAR FENDER INNER BOARD BOTTOM LH		1.00	Sn	301.20	20.00	240.96	Y	X
41	REAR SIDE OUTER PANEL LH		N	1.00	Sn	286.00	228.80	Y	X
42	REAR FENDER INNER BOARD TOP LH		1.00	Sn	363.40	20.00	290.72	Y	X
43	REAR FENDER LH		1.00	N	586.80	20.00	469.44	Y	X
44	REAR FENDER INNER TRIM LH		my CM	1.00	Sn	301.00	240.80	Y	✓
46	EXHAUST MUFFLER		1.00	N	585.40	20.00	468.32	Y	X
47	EXHAUST PIPE CENTRE		1.00	N	1288.60	20.00	1030.88	Y	X
48	EXHAUST PIPE MOUNTINGS		1.00	Sn	96.00	20.00	76.80	Y	X
49	KEYLESS SENSOR	108	Nd	1.00		20.00	304.00	Y	✓

TOTAL (PARTS) :

18448.70

14758.96

SPECIAL NETT ITEM

1	REAR BUMPER CLIPS (1 SET)		Nn	1.00	50.00	0.00	50.00	Y	✓
2	TAILGATE GLASS INNER SEAL		Nn	1.00	50.00	0.00	50.00	Y	20Sn
3	TAILGATE GLASS SEALANT		Nn	1.00	50.00	0.00	50.00	Y	40Sn
4	TAILGATE GLASS CLEANER & PRIMER		Nn	1.00	50.00	0.00	50.00	Y	X
5	TAILGATE INNER BOARD CLIPS (1 SET)		Nn	1.00	50.00	0.00	50.00	Y	✓
6	REAR NUMBER PLATE		Sn	1.00	50.00	0.00	50.00	Y	X
7	REAR END PANEL SEALANT		Nn	1.00	80.00	0.00	80.00	Y	30Sn
8	REAR FENDER INNER SHIELD CLIPS (1 SET)		Nn	1.00	50.00	0.00	50.00	Y	X
9	REAR FENDER INNER BOARD CLIPS(1 SET)		Nn	1.00	50.00	0.00	50.00	Y	X
10	REVERSE SENSOR		CR1	1.00	480.00	0.00	480.00	Y	200Sn
11	TAILLAMP INNER CLIPS (1 SET)		Nn	1.00	50.00	0.00	50.00	Y	X
12	SPARE TYRE INSULATOR PAD		Nn	1.00	280.00	0.00	280.00	Y	X
13	SPARE TYRE PANEL SEALANT		Nn	1.00	80.00	0.00	80.00	Y	X
14	1/4 GLASS SEALANT		Nn	1.00	50.00	0.00	50.00	Y	X
15	1/4 GLASS INNER SEAL		Nn	1.00	50.00	0.00	50.00	Y	X
16	1/4 GLASS CLEANER & PRIMER		Nn	1.00	50.00	0.00	50.00	Y	X

TOTAL (PARTS) :

1520.00

1520.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	1.00	1800.00	0.00	1800.00	Y	6001
2	SPRAY PAINTING ON AFFECTED AREA	1.00	1600.00	0.00	1600.00	Y	6001
3	R&R TAILGATE COMPONENTS	1.00	120.00	0.00	120.00	Y	601
4	R&R TAILGATE GLASS	1.00	120.00	0.00	120.00	Y	✓
5	R&R SPARETYRE BOARD,CARPET,TRIMS	1.00	120.00	0.00	120.00	Y	601
6	R&R SEATS & CARPET TO ASSIST REPAIR	1.00	120.00	0.00	120.00	Y	501
7	R&R REVERSE SENSOR & CALIBRATION	1.00	120.00	0.00	120.00	Y	601
8	RESPRAY TUFF KOTE ON ACC AREAS	1.00	120.00	0.00	120.00	Y	201
9	CHECK & REPAIR WIRING SYSTEM	1.00	120.00	0.00	120.00	Y	
10	R&R EXHAUST PIPE SYSTEM	na 1.00	380.00	0.00	380.00	Y	X
11	R&R 1/4 GLASS ASSY	na 1.00	120.00	0.00	120.00	Y	X
			4740.00		4740.00		
TOTAL PARTS & LABOUR			24708.70		21018.96		

EXCESS : : S\$

NO. OF DAY : 03

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY PART OR LUMP-SUM : S\$

DATE OF SURVEY : 28 / 5 / 21

SURVEY BY :

CONTACT NO :

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.