

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 25 May 2021

Preliminary Advice

Vehicle No	: SKV5426B	Accident Date	: 23/05/2021
Make	: MITSUBISHI OUTLANDER	Policy No.	: MPC20P00152200
Assignment Date	: 25/05/2021	Excess	: S\$0.00
Date of Inspection	: 25/05/2021	Est. Duration of Repair	: 5
Inspection At	: ALAN'S UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE, #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,281.90
Revised Amount	:S\$	5,177.60
Check Items (Estimated)	:S\$	1,576.30
Total	:S\$	6,753.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	39,477.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,523.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :