

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : LEE JIT CHOON
BLK 72 FLORA ROAD #04-26
SINGAPORE 506915

TP claim
Xiao Chun

Estimate No: EST1506976
Date: 25 May 2021
Policy No: PNPV2020-00002619
Veh Reg No: SLW8255R
Make/Model: KIA FORTE K3 1.6A
Chassis No: KNAFJ411MJ5756392
Engine No: G4FGHH688342
Reg. Date: 05/03/2018

ATTN: CHINA TAIPING
Your Ref No: TP 0521-6375
Claim Type: Third Party
Accident Date: 23/05/2021
TP Veh Reg No: SKM 1322 R

Estimate Repair Cost to Vehicle No :SLW8255R

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	633.00	1 PC	633.00	x
2 FRONT BUMPER CLIPS	4.80	10 PC	48.00	+
3 FRONT BUMPER SIDE HOLDER - LH	13.60	1 PC	13.60	+
4 FRONT BUMPER SIDE HOLDER - RH	13.60	1 PC	13.60	+
			708.20	
		Less 10%	70.82	637.38
Labour				
5 TO KNOCK OUT DENTS,RH FRONT FENDER, REMOVE, REPLACE ACCIDENT PARTS	350.00	1 JOB	350.00	x
6 TO RESPRAY PAINT ON ACCIDENT PORTIONS: FRONT BUMPER & RH FRONT FENDER	450.00	1 JOB	450.00	400
7 TO CHECK WIRING	20.00	1 JOB	20.00	+
			820.00	820.00
Total			S\$ 1,457.38	
Add GST @ 7%			102.02	
Total Amount Payable			S\$ 1,559.40	

TOTAL: SINGAPORE DOLLAR ONE THOUSAND FIVE HUNDRED FIFTY NINE AND CENTS FORTY ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

Adrian Li
P/P 03/06/21
02 Days

total: 400 (P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: