

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|---|--|-----------------|--------------------|--|
| | CHINA TAIPING IN | ISURANCE (S) PTE LTD | Ref: | CS/CTI21006154/Aqc | |
| | 3 ANSON ROAD # SPRINGLEAF TOV | 16-00 VERSINGAPORE 079909 | Date | e: 27/05/2021 | |
| | | | Cod | e: CTI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SKM 1322R | Veh. Inspected | SLW 8255R | |
| | Policy No. | DMPCSNA00160022004 | Coverage (\$) | 0.00 | |
| | Claim No. | SNM21D202960/C02/LEWLC | Excess (\$) | 0.00 | |
| | Assign From | JENNY LEW | Assign Date | 27/05/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | | c.c | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | | Colour | | |
| | Odometer | - | Steering | | |
| | Brakes | | Modification | | |
| | General | | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | | | mm | |
| | L/H Front Tyre | | | mm | |
| | R/H Rear Tyre | | | mm | |
| | L/H Rear Tyre | | | mm | |
| 4. | Description of Damages | | | | |
| | | | | | |
| 5. General Information | | | | | |
| | Accident Date | 23/05/2021 | Inspection Date | 03/06/2021 | |
| | Survey held at | PROGRESSIVE CAR CARE PTE LTD | | | |
| | | BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716 | | | |
| 5a. | Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |