

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159946
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 58511

Date Estimated : 25/05/2021

Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

1561858

- ESTIMATE REPAIR FOR -

Woo Foong Yee (Hu FengYi)
18 Leicester Road
#18-02

Singapore 358847

- ACCOUNT - 163385

Ltd. China Taiping

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG632K	WBA6V12030ED05459	30/11/2018	216i Gran Tourer	53222

DESCRIPTION

To replace repape rear bumper, tailgate and attachments.

1700 2,550.00

To painting rear bumper and tailgate.

1972 2,016.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To remove and install rear windscreen glass to facilitate repair.

574.00

To conduct water leak tests.

75.00

To carry out body cavity preservation.
(Per panel).

112 118.00

Sundries.

? 150.00

Total Labour 1: 5,897.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,216.40	1,216.40
REAR BUMPER CARRIER	1	460.40	460.40
REAR BUMPER TRIM STRIP (BLACK)	1	72.20	72.20
REAR BUMPER PANEL PRIMED (LINES PDC)	1	1,050.65	1,050.65
LETTERING 216	1	64.75	64.75
GROMMET	2	0.80	1.60
BUMP STOP	10	3.20	32.00
PLAQUE 82MM	1	71.95	71.95
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) WINDSCREEN SEALANT (2 X KLE)	2	175.35	350.70
(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	1	27.85	27.85

EXCESSIVE PAINT

Mr. Yeo Hock Tin
Supervisor
No. 9188 1767



supplementary

Estimate No. : **b1 58511**
Date Estimated : **25/05/2021**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Woo Foong Yee (Hu FengYi)
18 Leicester Road
#18-02

Singapore 358847

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG632K	WBA6V12030ED054	30/11/2018	216i Gran Tourer	53222

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# Transfer lock mechanism to new bootlid	504.00	0.00	504.00
--	--------	------	--------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING NUT	1.00	2.00	0.00	2.00
# PLAQUE 74MM	71.95	1.00	0.00	71.95
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0.00	263.10

SUPPLEMENTARY ITEMS

Total Labour :	504.00
Total Parts :	337.05