

IMPERIUM AUTOMOTIVE

25 Kaki Buki Road 4 #01-49 Synergy @ KB Singapore 417800
 Tel: 9748 9940 Fax: 6346 7213

not authorized
 28/5/21
 2/5 @ 3700/
 5 days
 when ph. After repair

Vehicle No.: SJY 8206X

Model: Mitsubishi Lancer

QTY List Price:

Prices \$

1	Boot Lip	<i>n</i>	695.00	X
1	Boot Lid Logo	<i>ncc</i>	48.00	✓
1	Boot Lid "C&C" Emblem	<i>ncc</i>	58.00	✓
1	Rear Bumper	<i>n.s</i>	732.00	—
2	Rear Bumper Reflector @ 58.00	<i>o/s cre</i>	116.00	<i>1pc</i>
1	Rear Bumper Top Beam	<i>n</i>	115.00	X
1	Rear Bumper Reinforcement	<i>37</i>	375.00	—
2	Rear Bumper Side Retainer @ 45.00	<i>37</i>	90.00	<i>1pc</i>
6	Rear Bumper Clip @ 4.50	<i>233</i>	27.00	—
1	Rear Bumper Tow Hook Cover	<i>233</i>	28.00	—
2	Rear License Plate Lamp @ 48.00	<i>7011</i>	96.00	X
1	Rear End Panel	<i>11</i>	435.00	—
1	Rear Smart Keyless Room Antenna	<i>11</i>	186.00	X
1	Rear Exhaust Pipe	<i>11</i>	543.00	—
1	Rear Taillamp (R)	<i>11</i>	342.00	X

Less 10%

Subtotal 3886.00
 -388.6
 Subtotal 3497.40

Special Nett Items

1	Rear License Plate W Holder	<i>one</i>	50.00	<i>40</i>
1 set	Rear Sensor	<i>one</i>	300.00	<i>200</i>
1 set	Rear Bumper Lower Spoiler		850.00	✓
1	Rear Boot Lid Sticker	<i>11</i>	80.00	X

Subtotal 1280.00

Labour Charges:

To remove, replaced damaged lamps and check up rear wiring.	120.00	<i>30</i>
To remove, refit rear reverse sensor	100.00	<i>50</i>
To apply undercoating	120.00	<i>30</i>
Panel Beating	1000.00	<i>600</i>
To respray painting on affected areas	1000.00	<i>900</i>

Subtotal 2340.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 7117.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: Page 1

p-2173
10%
p-1955.70
s.n-1090.00
2-1610.00
4655.7
3724