



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 38442

DATE : 03/05/2021
CLAIM NO. : 11730
POLICY NO. : V0107670

FROM : HASRIANAH

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

VEHICLE NO. : FBQ8056Z
MAKE/MODEL : KYMCO / SUPER JOCKEY150

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET BELLY PAN	REPLACE	4.00	\$7.00	28.00
2	Stock Availability (Days): 45 CHAIN BOX (STAINLESS STEEL) 2MM P/N: 24196 - (REPORTED BY USER)	REPLACE	2.00	\$6.00	12.00
3	COLLAR MAINSTAND P/N: 68850	REPLACE	2.00	\$7.00	14.00
4	Stock Availability (Days): 1 COVER FRONT (BLACK) P/N: 64032	REPLACE	1.00	\$147.00	147.00
5	Stock Availability (Days): 1 COVER LH SIDE P/N: 67194	REPLACE	1.00	\$129.00	129.00
6	Stock Availability (Days): 1 COVER RH B BODY P/N: 67176	REPLACE	1.00	\$41.00	41.00
7	Stock Availability (Days): 1 COVER RH SIDE P/N: 67189	REPLACE	1.00	\$129.00	129.00
8	Stock Availability (Days): 1 COVER TRANSMISSION	REPLACE	1.00	\$196.00	196.00
9	Stock Availability (Days): 45 COVER UNDER COMP P/N: 67227	REPLACE	1.00	\$24.00	24.00
	Stock Availability (Days): 1				

*38442 *

Our Safety Consultants hence notify
the following:
• The resurvey is before/after spray painting
• The resurvey is subject to confirmation
• The resurvey is on a "Without Prejudice" basis
• The resurvey is allowed
• The resurvey must be resurveyed and
is subject to final approval from Insurance Company

bizSAFE



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-10-03
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
10	EXHAUST ASSY P/N: 67166 Stock Availability (Days): 45	REPLACE	1.00	\$721.00	721.00 X
11	GASKET COVER AUTOCLUTCH P/N: 67195 Stock Availability (Days): 1	REPLACE	1.00	\$40.00	40.00 X
12	HOOK HOLDER (S/STEEL) P/N: 38796 - (REPORTED BY USER)	REPLACE	4.00	\$6.00	24.00 X
13	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS		7.00	\$63.00	441.00
14	LEVER BRAKE RH P/N: 67431 Stock Availability (Days): 1	REPLACE	1.00	\$17.00	17.00
15	LOCK BOX REAR (3 INCH) P/N: 12369 - (REPORTED BY USER)	REPLACE	1.00	\$16.00	16.00 X
16	REPAIR REAR FIBER BOX - (REPORTED BY USER)	Repair	1.00	\$168.00	168.00 ✓
17	RUBBER SOFT ROUND TYPE <i>3 checks price</i> Stock Availability (Days): 1	REPLACE	00.00	\$3.00	300.00 ?
18	SPRAY PAINT ON REAR FIBRE BOX - (REPORTED BY USER)	Spray	1.00	\$259.00	259.00
19	STAND MAIN P/N: 67230 Stock Availability (Days): 1	REPLACE	1.00	\$107.00	107.00 ✓
20	STICKER (SINGAPORE POST) BOX REAR P/N: 39656 - (REPORTED BY USER)	REPLACE	1.00	\$47.00	47.00 ✓
21	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	Supply/Install	1.00	\$56.00	56.00
SUB TOTAL					\$2,916.00
GST @ 7 %					\$204.12
GRAND TOTAL (SGD)					\$3,120.12

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By

*38442 *



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001:2015

Quotation Nos 38442

(Page 3 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
-----	-------------	--------	-----	------------	--------



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38442 *

bizSAFE₃



Address: No. 6, Debu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2833-1-0183
ISO 9001:2015