



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

NO. : 38442

DATE : 03/05/2021

CLAIM NO. : 11730

POLICY NO. : V0107670

FROM : HASRIANAH

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO. : FBQ8056Z

MAKE/MODEL : KYMCO / SUPER JOCKEY150

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET BELLY PAN	REPLACE	4.00	\$7.00	28.00
	Stock Availability (Days): 45				
2	CHAIN BOX (STAINLESS STEEL) 2MM P/N: 24196 - (REPORTED BY USER)	REPLACE	2.00	\$6.00	12.00
3	COLLAR MAINSTAND P/N: 68850 Stock Availability (Days): 1	REPLACE	2.00	\$7.00	14.00
4	COVER FRONT (BLACK) P/N: 64032 Stock Availability (Days): 1	REPLACE	1.00	\$147.00	147.00
5	COVER LH SIDE P/N: 67194 Stock Availability (Days): 1	REPLACE	1.00	\$129.00	129.00
6	COVER RH B BODY P/N: 67176 Stock Availability (Days): 1	REPLACE	1.00	\$41.00	41.00
7	COVER RH SIDE P/N: 67189 Stock Availability (Days): 1	REPLACE	1.00	\$129.00	129.00
8	COVER TRANSMISSION Stock Availability (Days): 45	REPLACE	1.00	\$196.00	196.00
9	COVER UNDER COMP P/N: 67227 Stock Availability (Days): 1	REPLACE	1.00	\$24.00	24.00

*38442 *

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	EXHAUST ASSY P/N: 67166 Stock Availability (Days): 45	REPLACE	1.00	\$721.00	721.00
11	GASKET COVER AUTOCLUTCH P/N: 67195 Stock Availability (Days): 1	REPLACE	1.00	\$40.00	40.00
12	HOOK HOLDER (S/STEEL) P/N: 38796 - (REPORTED BY USER)	REPLACE	4.00	\$6.00	24.00
13	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	L	7.00	\$63.00	441.00
14	LEVER BRAKE RH P/N: 67431 Stock Availability (Days): 1	REPLACE	1.00	\$17.00	17.00
15	LOCK BOX REAR (3 INCH) P/N: 12369 - (REPORTED BY USER)	REPLACE	1.00	\$16.00	16.00
16	REPAIR REAR FIBER BOX - (REPORTED BY USER)	L * Local repair Repair	1.00	\$168.00	168.00
17	RUBBER SOFT ROUND TYPE Stock Availability (Days): 1	REPLACE	00.00	\$3.00	300.00
18	SPRAY PAINT ON REAR FIBRE BOX - (REPORTED BY USER)	L Spray	1.00	\$259.00	259.00
19	STAND MAIN P/N: 67230 Stock Availability (Days): 1	REPLACE	1.00	\$107.00	107.00
20	STICKER (SINGAPORE POST) BOX REAR P/N: 39656 - (REPORTED BY USER)	REPLACE	1.00	\$47.00	47.00
21	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	L Supply/Install	1.00	\$56.00	56.00

SUB TOTAL

\$2,916.00

GST @ 7 %

\$204.12

GRAND TOTAL (SGD)

\$3,120.12

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

*38442

*

Acknowledge & Accepted By

1-911
102
819.90
1589.90

bizSAFE₃
 CERT NO: 2002-1-0363
 ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38442 *

bizSAFE₃

