

CC3/ALG 21006193/AVC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 2100216570Claims No. 3459074605 SGSum Insured: \_\_\_\_\_ Excess: 1300

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR. Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SCM9200B Yr Regn: 2009, JuneType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 c.c. 1798Colour: Bronze A/C: Insured / Std / NI / NASp. Reading: 122708 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZZ8K79A235653Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 225/55R16R: 225/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. 10/5/21 D.O.I. 27/05/21Survey held at PremiumDes. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD ALG</u>
	<u>COE Expiry: 31/03/29</u>
	<u>MV: 76K</u>
	<u>PV: 25.9K</u>
	<u>Nett: 50.1K</u>
	<u>Final fig \$ 8424.80</u>

Date/Time, File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / L.B.B. \$ \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Wash end (\$)

Survey Fee:

Transportation:

3 + PS. \$

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	453H
Vehicle Details	
Vehicle No.:	SCM9200B
Vehicle to be Exported:	No
Intended Deregistration Date:	27 May 2021
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8T FSI MU CVT ABS D/AB 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	CDH051315
Chassis No.:	WAUZZZ8K79A235653
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$35,931.00
Original Registration Date:	25 Jun 2009
First Registration Date:	25 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$35,931.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2029
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$33,018.00
COE Rebate Amount:	\$25,899.00
Total Rebate Amount:	\$25,899.00

The information contained herein is correct as at 27 May 2021

OK



**CONNECTING CAR BUYERS & SELLERS.**  
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

BMW 2 Series 216i Gran Tourer Luxury.



Very Low Mileage, Warranty And  
Service Package Till 2023.  
Direct Owner


[Browse by Category](#)

15 vehicles

[Sort by Date Posted](#)
[20 results/page](#)
[Advanced Search](#)

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
audi a4		Any	Any	> 10 year(s) old	Any	Any	Any	Available



**Audi A4 Cabriolet 2.0A TFSI S-Line (COE till 09/2028)**

**\$66,700**

\$9,080 /yr

29-Sep-2008

1,984 cc

143,000 km

Sports

Available

No Modification, Kept Stock And Fully Rebuilt With More Than \$10K Spend Recently, Brand New Hydraulic System For Hood, Engine Fully Overhauled With Many Others Parts Changed. 12 Month Warranty With 3 Free Servicing Package. Spacious 5 Seater Convertible, Driving...

Posted: 08-May-2021 Tags: 2008 Audi A4, Audi A4, Audi, A4



**Audi A4 1.8A TFSI MU (COE till 08/2028)**

**\$58,800**

\$8,090 /yr

06-Oct-2008

1,798 cc

-

Luxury

Available

Premium Brown Leather Seats, In Great Condition, Taken Care By Meticulous Owner, Service Done Regularly With No Repairs Needed! 100% Accident Free. Careful Owner And Well Maintained, Selling Due To Upgrade! Consignment Unit, Flexible Bank/In House Loan Avail...

Posted: 27-May-2021 Tags: 2008 Audi A4, Audi A4, Audi, A4



**Audi A4 Cabriolet 2.0A TFSI S-Line (COE till 01/2029)**

**\$60,000**

\$7,850 /yr

15-Jan-2009

1,984 cc

175,000 km

Sports

Available

Genuine Mileage, No Repair Needed. Workshop Warranty Option Available! Drive Away With A Peace Of Mind. Well Maintained. Perfect Gearbox!

Posted: 07-May-2021 Tags: 2009 Audi A4, Audi A4, Audi, A4



**Audi A4 1.8A TFSI MU S-Line (COE till 01/2029)**

**\$74,000**

\$9,630 /yr

26-Feb-2009

1,798 cc

-

Luxury

Available

Pristine Condition! Stage 3 Tuned By Reputable Workshop. 340HP 500NM With All Legal Modifications. Wear And Tear Recently Replaced No Repairs Needed! Many Goodie Under The Hood. Come On Down To Take A Look At This Beauty. Bank/In House Up To 100% Loan, F...

Posted: 13-May-2021 Tags: 2009 Audi A4, Audi A4, Audi, A4

**GET YOUR COE RENEWAL LOAN**

**Is your COE expiring? Let us help you renew it!**

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



**Audi A4 1.8A TFSI MU (COE till 02/2024)**

**\$30,000**

\$10,860 /yr

25-Mar-2009

1,798 cc

169,000 km

Luxury

Available

100%Loan Approval!Bank And In House Loan Available!Unbelievable High Trade In!Excellent Condition!View To Belive,Hurry Call Our Sales Teams Arrange. For Car Viewing Before It Gone

Edmund Motor Pte Ltd

Posted: 13-Apr-2021 Tags: 2009 Audi A4, Audi A4, Audi, A4



**Audi A4 2.0A TFSI Quattro S-Line (COE till 12/2028)**

**\$72,000**

\$9,470 /yr

25-Sep-2009

1,984 cc

-

Luxury

Available

A Lot Have Been Done Up To The Car. Engine And Gear Box Have Been Overhauled. Feel Free To Text Me For Viewing. No Agents And Dealers. Thanks.

Posted: 16-May-2021 Tags: 2009 Audi A4, Audi A4, Audi, A4

[Compare](#)



# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Low Yin Leng  
Period of Insurance : 25 Jun 2020 To 24 Jun 2021  
Engine No. : CDH051315  
Chassis No. : WAUZZZ8K79A235653

Vehicle No. : SCM9200B  
Policy No. : 2100216570-10  
Endorsement No. :  
Issued Date : 17 May 2020

### ABOUT THE COVER

Make/Model : AUDI A4 1.8T FSI MU (LIMITED EDITION)  
Engine Capacity/Tonnage : 1,798.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2009  
Insuring with COE/PARF : Yes

#### Person or Classes of Persons Entitled to Drive\* :

- a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$1300 Theft - \$0 Flood Cover - \$1300

#### Section 2

Property Damage - \$0

Windscreen : \$100

#### Named Driver and Excess (where applicable)

Low Yin Leng - \$1300 (Own Damage), \$1300 (Flood Cover), Chua Jon Yen - \$1300 (Own Damage), \$1300 (Flood Cover), Liow Boon Huat - \$1300 (Own Damage), \$1300 (Flood Cover)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63962323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: UOB LIMITED

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.

AIGSGMOBILEAPP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0445/2021/GW  
**DATE** : 25-May-21  
**WIP** :

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MDM LOW YIN LENG  
**ADDRESS** : 1 TREVOSE PLACE  
SINGAPORE 297985  
**TELEPHONE** : HP +65 96191720  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2100216570-10  
**VEHICLE NO** : **SCM 9200 B**  
**MODEL CODE** : AUDI A4 1.8 TFSI MU  
**MODEL YEAR** : 25/6/2009  
**ENGINE NO** : CDH 051315  
**CHASSIS NO** : WAUZZZ8K79A235653  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**DATE OF ACCIDENT** : 10-May-21  
**PLACE OF LOCATION** : BUKIT TIMAH RD, JUNCTION OF BALMAROL RD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCM 9200 B**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS , OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	✓ ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	250 ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,200.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	500 ✓
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, HINGES AND BONNET.	\$	3,200.00	1100 1650
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 10,552.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$ 2,560.00	<i>✓ 2048</i>
2	FRONT BUMPER FIXING PARTS <i>men</i>	1	\$ 259.00	<i>+</i>
3	FRONT BUMPER SUPPORT-LH/RH <i>men</i>	2	\$ 186.00	<i>+</i>
4	FRONT BUMPER GUIDE SECTION-LH/RH <i>men</i>	2	\$ 88.00	<i>+</i>
5	FRONT BUMPER COVER <i>cracked</i>	1	\$ 127.00	<i>✓ 101.60</i>
6	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>men</i>	1	\$ 176.00	<i>+</i>
7	FRONT FOAM FILLIER PIECE <i>?</i>	1	\$ 124.00	<i>? X</i>
8	FRONT AIR GUIDE GRILLE-LH/RH <i>men</i>	2	\$ 344.00	<i>+</i>
9	FRONT BUMPER COVER SPACER PANEL <i>men</i>	1	\$ 98.00	<i>✓ 78</i>
10	FRONT BUMPER BRACKET-LH/RH <i>?</i>	2	\$ 456.00	<i>? X</i>
11	FRONT REINFORCEMENT BEAM <i>Rehd</i>	1	\$ 926.00	<i>✓ 740.80</i>
12	STICKER FOR 'SIGN CAUTION' <i>3m</i>	1	\$ 14.00	<i>✓ 10.88</i>
13	STICKER FOR AIR CONDITIONER <i>3m</i>	1	\$ 30.00	<i>✓ 24</i>
14	RADIATOR GRILLE <i>cracked</i>	1	\$ 706.00	<i>✓ 564.40</i>
15	RADIATOR GRILLE COVER <i>?</i>	1	\$ 58.00	<i>? X</i>
16	SIGNAL HORN-LH/RH <i>3m</i>	2	\$ 402.00	<i>+</i>
18	SIGNAL HORN BRACKET-LH/RH <i>3m</i>	2	\$ 50.00	<i>+</i>
19	BONNET <i>Repair</i>	1	\$ 2,274.00	<i>X</i>
20	BONNET ATTACHMENT PARTS <i>men</i>	1	\$ 168.00	<i>+</i>
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 9,046.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET LID HINGE-LH/RH <i>ne n</i>	2	\$ 148.00	+
22	BONNET CATCH HOOK <i>ne n</i>	1	\$ 140.00	+
23	BONNET EDGE PROTECTION <i>ne n</i>	1	\$ 28.00	+
24	BONNET LID LOCK WITH MICRO SWITCH <i>ne n</i>	1	\$ 214.00	+
25	BONNET LOCK COVER <i>ne n</i>	1	\$ 23.00	+
26	FRONT FENDER-RH <i>Regis</i>	1	\$ 990.00	+
27	FRONT FENDER ATTACHMENT PARTS-RH <i>ne n</i>	1	\$ 57.00	+
28	FRONT FENDER BRACE-RH LOWER	1	\$ 118.00	+
29	FRONT FENDER BRACKET-RH FRONT	1	\$ 53.00	+
30	FRONT FENDER BRACKET-RH REAR	1	\$ 49.00	+
31	FRONT WHEEL HOUSING LINER-RH	1	\$ 240.00	+
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>ne n</i>	1	\$ 45.00	+
33	HEADLIGHT MOUNTING-LH/RH ?	2	\$ 236.00	? 914.40
34	HEADLIGHT BRACKET-LH/RH ?	2	\$ 156.00	? X
35	FRONT LOCK CARRIER <i>ne n</i>	1	\$ 1,016.00	? X
36	RADIATOR SUPPORT BRACKET-LH/RH <i>ne n</i>	2	\$ 90.00	? X
37	A/C CONDENSER <i>ne n</i>	1	\$ 743.00	+
38	A/C CONDENSER O-RING	1	\$ 10.00	+
39	A/C CONDENSER SEAL RING	1	\$ 7.00	+
40	A/C REGFRIGERANT LINE O-RING	1	\$ 10.00	+
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 4,373.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT TEMPERATURE SENSOR BRACKET ?	\$	19.00	? X
42	RADIATOR AIR GUIDE-LH/RH ?	2 \$	56.00	? X
43	SEALING STRIP <i>new</i>	\$	23.00	X
44	HEADLIAMP-LH/RH <i>RH ut</i>	2 \$	4,334.00	<del>2167</del> 2167 1733.60
45	FRONT NO. PLATE <i>Dented</i>	S/N \$	60.00	✓ 60
46	SUNDRIES ?	\$	300.00	? 17.12
<b>TOTAL SPARE PARTS</b>		:	\$	<b>18,211.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>10,552.00</b>
<b>GRAND TOTAL</b>		:	\$	<b>28,763.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adria L  
27/05/21

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Not Authorised, 04 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCM 9200 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. S/N S	360.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N S	700.00	250
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. S/N S	1,200.00	X
* 4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, (RHS FRONT FENDER) AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. S	4,900.00	750. H.S.
* 5	TO RESPRAY FRONT BUMPER (RHS FRONT FENDER) HINGES AND BONNET. S	3,200.00	1650. H.S.
6	TO CARRY OUT DIAGNOSTIC CHECK. S/N S	192.00	✓ H.S.
TOTAL LABOUR CHARGES		: \$ 10,552.00	


+ 1 working days

H.S.

Car-in 15/6/21. WIP: 29118

**PREMIUM AUTOMOBILES**

Kiam



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5CM 9200 B**

Atti - Ashim

4 day

**DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 2,560.00	✓
2	FRONT BUMPER FIXING PARTS <i>Rehnd</i>	1	\$ 259.00	✓
3	FRONT BUMPER SUPPORT-LH/RH <i>Rehnd</i>	2	\$ 186.00	✓
4	FRONT BUMPER GUIDE SECTION-LH/RH <i>Rehnd</i>	2	\$ 88.00	✓
5	FRONT BUMPER COVER <i>Rehnd</i>	1	\$ 127.00	✓
6	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>Rehnd</i>	1	\$ 176.00	✓
7	FRONT FOAM FILLIER PIECE ?	1	\$ 124.00	?
8	FRONT AIR GUIDE GRILLE-LH/RH <i>Rehnd</i>	2	\$ 344.00	✓
9	FRONT BUMPER COVER SPACER PANEL <i>Rehnd</i>	1	\$ 98.00	✓
10	FRONT BUMPER BRACKET-LH/RH ?	2	\$ 456.00	?
11	FRONT REINFORCEMENT BEAM <i>Rehnd</i>	1	\$ 926.00	✓
12	STICKER FOR 'SIGN CAUTION' <i>Rehnd</i>	1	\$ 14.00	✓
13	STICKER FOR AIR CONDITIONER <i>Rehnd</i>	1	\$ 30.00	✓
14	RADIATOR GRILLE <i>Rehnd</i>	1	\$ 706.00	✓
15	RADIATOR GRILLE COVER ?	1	\$ 58.00	?
16	SIGNAL HORN-LH/RH <i>Rehnd</i>	2	\$ 402.00	✓
18	SIGNAL HORN BRACKET-LH/RH <i>Rehnd</i>	2	\$ 50.00	✓
19	BONNET <i>Rehnd</i>	1	\$ 2,274.00	✓
20	BONNET ATTACHMENT PARTS <i>Rehnd</i>	1	\$ 168.00	✓
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 9,046.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET LID HINGE-LH/RH <i>Not in</i>	2	\$ 148.00	+
22	BONNET CATCH HOOK <i>Not in</i>	1	\$ 140.00	+
23	BONNET EDGE PROTECTION <i>Not in</i>	1	\$ 28.00	+
24	BONNET LID LOCK WITH MICRO SWITCH <i>Not in</i>	1	\$ 214.00	+
25	BONNET LOCK COVER <i>Not in</i>	1	\$ 23.00	+
26	FRONT FENDER-RH <i>Regis</i>	1	\$ 990.00	+
27	FRONT FENDER ATTACHMENT PARTS-RH <i>Not in</i>	1	\$ 57.00	+
28	FRONT FENDER BRACE-RH LOWER <i>Not in</i>	1	\$ 118.00	+
29	FRONT FENDER BRACKET-RH FRONT <i>Not in</i>	1	\$ 53.00	+
30	FRONT FENDER BRACKET-RH REAR <i>Not in</i>	1	\$ 49.00	+
31	FRONT WHEEL HOUSING LINER-RH <i>Not in</i>	1	\$ 240.00	+
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not in</i>	1	\$ 45.00	+
33	HEADLIGHT MOUNTING-LH/RH <i>Not in</i>	2	\$ 236.00	118.
34	HEADLIGHT BRACKET-LH/RH <i>Not in</i>	2	\$ 156.00	+
35	FRONT LOCK CARRIER <i>Not in</i>	1	\$ 1,016.00	+
36	RADIATOR SUPPORT BRACKET-LH/RH <i>Not in</i>	2	\$ 90.00	+
37	A/C CONDENSER <i>Not in</i>	1	\$ 743.00	+
38	A/C CONDENSER O-RING <i>Not in</i>	1	\$ 10.00	+
39	A/C CONDENSER SEAL RING <i>Not in</i>	1	\$ 7.00	+
40	A/C REFRIGERANT LINE O-RING <i>Not in</i>	1	\$ 10.00	+
SUB TOTAL SPARE PARTS		:	\$ 4,373.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT TEMPERATURE SENSOR BRACKET <i>Dented</i>	\$	19.00	<i>Z</i>
42	RADIATOR AIR GUIDE-LH/RH ?	2	\$ 56.00	<i>?</i>
43	SEALING STRIP <i>seen</i>	\$	23.00	<i>X</i>
44	HEADLIAMP-LH/RH <i>RH out</i>	2	\$ 4,334.00	<i>2167</i>
45	FRONT NO. PLATE <i>Dented</i>	S/N	\$ 60.00	<i>✓</i>
46	SUNDRIES ?	\$	300.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 18,211.00	
TOTAL LABOUR CHARGES		:	\$ 10,552.00	
GRAND TOTAL		:	\$ 28,763.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

*Adrian King*  
*H.S.*  
*Resurveyed*