

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0464/2021/HR
DATE : 31-May-21
WIP : 29203

Ceilia.

3079.20 3 Days.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. BERNETTER NG BOON HWEE
ADDRESS : Blk 62 Dakota Crescent
#08-303
SINGAPORE 390062
TELEPHONE : HP +65 98628761
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210030405
VEHICLE NO : SLQ 202 C
MODEL CODE : Q3 1.5 TFSI S TRONIC
MODEL YEAR : 24/3/2021
ENGINE NO : CZD C23676
CHASSIS NO : WAUZZZF36M1062583
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-May-21
PLACE OF ACCIDENT : 5 STADIUM WALK, SG 397693
LEISURE PARK KALLANG BASEMENT CARPARK

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLQ 202 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500
4	TO RESRPAY FRONT BUMPER.	\$ 1,000.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,272.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SLQ 202 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>torn</i>	1	\$ 1,008.00	<i>✓</i>	806.40
2	FRONT BUMPER CONNECTING PIECE	1	\$ 145.00	<i>✓</i>	
3	FRONT BUMPER CLOSING ELEMENT LH <i>new</i>	1	\$ 59.00	<i>✓</i>	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	<i>x</i>	
5	FRONT BUMPER GRILLE - LH <i>new</i>	1	\$ 110.00	<i>x</i>	
6	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 190.00	<i>✓</i>	
7	FRONT BUMPER SPOILER <i>new</i>	1	\$ 383.00	<i>✓</i>	
8	FRONT BUMPER AIR GUIDE GRILLE LH <i>new</i>	1	\$ 153.00	<i>✓</i>	122.00
9	RADAIOR GRILLE	1	\$ 1,433.00	<i>x</i>	
10	RADAIOR GRILLE STRIKER PLATE	1	\$ 244.00	<i>x</i>	
11	FOAM FILLER PIECE	1	\$ 102.00	<i>x</i>	
12	FRONT REINFORCEMENT BEAM <i>new</i>	1	\$ 916.00	<i>x</i>	
13	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 123.00	<i>x</i>	
14	FRONT BUMPER GUIDE SECTION LH	1	\$ 39.00	<i>x</i>	
15	"CAUTION" SIGN STICKER	1	\$ 14.00	<i>x</i>	
16	FRONT PARKING AID SENSOR <i>new</i>	1	TBC	<i>x</i>	
17	FRONT PARKING AID SENSOR SEAL RING	1	\$ 14.00	<i>x</i>	
18	FRONT WHEEL HOUSING LINER LH	1	\$ 240.00	<i>x</i>	
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 101.00	<i>x</i>	
20	HEADLIGHT MOUNTING LH	1	\$ 118.00	<i>x</i>	
SUB TOTAL SPARE PARTS		:	\$ 5,609.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) - APPROVED, REMARKS (X) - NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 202 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LED HEADLIGHT LH	1	\$ 5,589.00	+
22	HEADLIGHT LIFT CYLINDER LH	1	\$ 210.00	+
23	HEADLIGHT LIFT CYLINDER HOSE	1	\$ 80.00	+
24	FRONT WHEEL ARCH COVER LH / RH	2	\$ 536.00	✓ 428.00 NEC
25	RADIATOR AIR GUIDE LH	1	\$ 38.00	+
26	RADIATOR AIR GUIDE UPPER	1	\$ 42.00	+
27	SUNDRIES		\$ 350.00	✗ NN
TOTAL SPARE PARTS		:	\$ 12,454.00	
TOTAL LABOUR CHARGES		:	\$ 3,272.00	
GRAND TOTAL		:	\$ 15,726.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.
bl-31/03/21

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

*Adrian Lim.
28/05/11*

*Not Authorised, 03 Days.
H.S.*

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULT NT