ASS. REG. BY: REF: A'G	21006208/KVf3
	SIGNMENT
Estimated Cost: Date:	Veh No: SUK 2008 Pyr Regn: 03, 2/
OUTP/WS/TP RES/OD RES/EVA/INV/MY	- Taxi / Prime Mover /
To Inspect Vehicle No:	Make: M. Wagon
-1W-4-1	- 4 GCC 300 CC 1991
of Tong Luck	Colour M. Blue A/C: Insured / Std / NI / NA
Insured:	Sp.Reading 4725 T/Radio: Insured / Std / NI / NA
Policy No. 099993623	Eng/No:
Claims No. 7205226894SG	CNO: WIN 25398 42F 855100
Sum Insured: Excess: 1700	Gen. Cond; 2000 Fair / Poor / Burnt
(Client's Record)	Steering: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inerder / Jammed / Leaked / Burnt or
	Modi: Nil / S/Rim / ST&A/Rim or Tyre Size: F: 235/66018
(Policy Condition)	Tyre Size: F: 235/60R18
Remark: The veh had commenced its N/S O/S	7.
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHT SU PIR I SUMI / TOYO / YOKO or
Bal. or Market Value: & 240/c	Front
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 9 mm R/Bal. 9
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 9 mm L/Bal. 9
Est. Repairs: O/ days Res.: Yes or No Lum Sum: //3// 4/ 3 Val: Yes or No	D.O.A. 20/5/21 D.O.I. 31/5/2021
Lum Sum:	Survey held at
CA / REV) REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	OIS Dods
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
45/0/04	
15/6/21 Kenneth confirmed \$2775.10 (Red	908,24%)
Onto/Time, File Pass to? : Prell. Report	
11	ays Of Repair: 1
Cuta/Time, File Return to?	esurvey No. of Trip: 1 Survey Fee:
n 16/6/21-Typist Add Fee:	: Site insp (\$
,	/////////////
Report Format: Merimen	Interview (\$) Fix 1%
Lump Sum / I.B.I: (\$ 2775.10	Tech Invs (\$) Others
	Weekend (\$
	1074



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

NOT Nothark NO

DATE : 28/05/2021

POLICY NO : 999995580

WEH REG NO : SLK2008R

MAKE/MODEL : MERCEDES 4MATIC (R1

CHASSIS NO : W1N253984

ENGINE NO : 2649208006

ESTIMATE

: QUOT202105-000070(00)

ATTN: MOTOR CLAIM DEPT

TEL : 6419 3000

YOUR REF NO

CLAIM TYPE

MAKE/MODEL: MERCEDES BENZ GLC300 4MATIC (R18 LED)

: W1N2539842F855100

: 26492080086791

REG. DATE

: 2021

ACCIDENT DATE : 20/05/2021

: OWN DAMAGE

Estimate Repair Cost to Vehicle No: SLK2008R

	Description	Quantity	Unit Price	Amount
	PARTS	GALL REPORTED	<u>S\$</u>	<u>S\$</u>
1	Stepboard garnish - RH		1,280.00	7, 1,280.00
2	Stepboard inner carrier- RH	1	360.00	1,200.00
3	Stepboard insert - RH	1	280.00	000.00
4	Stepboard top chrome - RH	1	1	- '-
5	Stepboard nubbed insert - RH (Front)	DOMESTIC CONTRACTOR	455.00	455.00
6		387.	30.00	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
× 7	Stepboard nubbed insert - RH (Rear)	the said of the design and	40.00	10.00
8	Stepboard clips - RH	17000	32.00	
	•	16	9.00	Ma 144.00
			Add 10%	2,621.00 6 262.10
	LABOUR			2,883.10
9	Labour charges to remove & refit above parts	Service of the second of	800.00	800.00
1.0	and the second of the second of the second of			800.00
		Section 1999	TOTAL	S\$ 3,683.10
			ADD GST @ 7%	257.82
			GRAND TOTAL	S\$ 3,940.92
INCA	PORE DOLLAR TURNS			-+ -,-+0.32

SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED FORTY AND CENTS NINETY-TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG

U¢K AUTO PTE LTD

SA0A215K000B-01 / Ajax Mars Pte Ltd ENTRY DATE & TIME: 20/05/2021 19:46 (SGT) SUBMITTED BY: Hashim VERSION: 2 (28/05/2021 11:02 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate onling liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/05/2021 19:46 (SGT) Date of Accident 20/05/2021 12:30 (SGT) Exact Location of Accident Singapore Additional Location Information TIONG BHARU MARKET (MSCP) UPPER LEVEL Country/State of Loss

Singapore

DETAILS OF OWN VEHICLE

1991

Vehicle Registration Number **SLK2008R** INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Company Reg No 1XXXXX778Z Email Address osman.affan@daimler.com Mobile Phone No (Phone) +65-68498118 Alternative Phone No (Office) +65-68498118

VEHICLE PARTICULARS

Mercedes Model GLC300 4MATIC (R18 LED) Variant Exact purpose for which vehicle was being used at time of Private use Are you claiming under your own insurance policy for repair to your vehicle? Yes Vehicle Category Private car Transmission Auto CC

INSURANCE COMPANY

Name of Insurance Company Type of Coverage AIG Asia Pacific Insurance Pte. Ltd. Fleet Policy Comprehensive Yes Policy Number 999995580 Cover Note Number

DRIVER

Name of Driver **CHOON HIN FATT** NRIC No SXXXX761.I

Accident report SA0A215K000B

Page 1 of 15

