

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21006220/KPA3Q2
Date: 19/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	YK999P	Insured Vehicle No :	SHD2013J
Date of Loss:	23/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002226

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YK999P		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C42158
Reg. Date:	12/01/2017 (Man. Year: 2016)	Chassis No:	FEB21EA21131
Colour:	White	Odometer:	283923 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Kenda 8 mm	Rear Left Side:	Kenda 6/6 mm
Front Right Side:	Kenda 8 mm	Rear Right Side:	Kenda 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,601.92	1,238.10	363.82	22.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	550.00	250.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,401.92	1,788.10	613.82	25.56
Approved Total (Overridden) (S\$)		1,400.00		

(S\$)	2,401.92	1,400.00	1,001.92	41.71
+ GST 7.00/7.00% (S\$)	168.13	98.00	70.13	41.71
Nett Amount (S\$)	2,570.05	1,498.00	1,072.05	41.71
+ Loss of Use (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,745.45		

INSPECTION

Date of Assignment: 28/05/2021

Date Inspected: 07/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Jun 2021)	
Parts:	N/A	mitsubishi canter 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YK999P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LICENSE PLATE LAMP	Serviceable	145.10 FL	*- FL
2	1		*N/S TAILLAMP	Broken	275.10 FL	*275.10 FL
3	1		*N/S TAILLAMP BRACKET	Bent	155.70 FL	*155.70 FL
4	1		*REAR BUMPER	Bent	450.00 FS	*450.00 FS
5	2		*REAR BUMPER BRACKET	Bent / Distorted	440.00 FS	*440.00 FS
6	1		*REAR CHASSIS FRAME CTR MEMBER	Repair	250.00 FS	*- FS
7	1		*REAR NO.PLATE	Bent	30.00 FS	*25.00 FS
					Sub Total (\$\$)	1,745.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	143.98
					Total Parts (\$\$)	1,601.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY REPLACED PARTS	New	200.00	150.00
2	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	600.00	400.00
Gross Labour Cost (\$\$)			800.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >