



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006229/Duf3e2	
			Date: 25/11/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4607M	Veh. Inspected	FG 2298L
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/05/21/2060	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	31/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA NMAX 155	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH3SG5680MK070193	Colour	BLACK / SILVER
	Odometer	5760 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70 R13	DUNLOP	2 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70 R13	DUNLOP	2 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/05/2021	Inspection Date	31/05/2021
	Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	