

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 22 June 2021

To : LKK

By Fax: 6256-4315

Attn : Bryan

Tel : 97237799

VEHICLE NO : FG 2298L

Yamaha NMAX 155

ACCIDENT DATE: 25 May 2021

Supplementary Items:

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Rear rim <i>distorted</i>	1	450.00 ✓
2 Swing Arm - Linkage RH <i>distorted</i>	1	275.00 ✓
3 Engine Mounting Bracket <i>distorted</i>	1	220.00 ✓
		<i>945.00</i>
Sub-Total		<i>850.50</i> 945.00
Less 10%		94.50
Sub-Total		850.50

Nett items

1 Align body frame		<i>250.00 80/-</i>
2 Remounting	<i>140.00</i>	<i>280.00 60/-</i>
Sub-Total		530.00
Nett Total		1,380.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

18/08/2021 @ 1730hrs

990.50

Bryan

Kindly revert upon completion. Thank you

LKK And

SG 98 MOTOR PTE LTD

8