

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref: CS/MSG21006267/T1qf3		
4 SHENTON WAY #21-01,SGX CENTRE 2		Date: 31/05/2021		
SINGAPORE 068807		Code: MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLV 1582Y	Veh. Inspected	SLP 1925Z	
Policy No.	257990 30001624024	Coverage (\$)	0.00	
Claim No.	0000400400 257990	Excess (\$)	0.00	
Assign From	MERIMEN (NOR AZIAN BINTE NOORDIN)	Assign Date	31/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/05/2021	Inspection Date	01/06/2021	
Survey held at	8 Kaki Bukit Avenue 4, #05-23 Premier			
Repairer	XIN YUN AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				