



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0460/2021/TF
DATE : 29-May-21
WIP : 29181

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838


OWNER'S NAME : SMP 2044 Y
ADDRESS : 80 LORONG K TELOK KURAU
#02-03
SINGAPORE 425710
TELEPHONE : HP +65 88281313
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900162090
VEHICLE NO : **SMP 2044 Y**
MODEL CODE : A3 SPORTSBACK 1.0 TFSI
MODEL YEAR : 16/9/2019
ENGINE NO : CHZ C35215
CHASSIS NO : WAUZZZ8V5LA002954
MILEAGE : 17845KM
DATE IN : 28-May-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-May-21
PLACE OF ACCIDENT : AIRPORT RD LEADING TO KPE TUNNEL



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 2044 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	✓
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	X
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1.5 \$ 2,450.00	750 ✓
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR. @ 550 x 3 + 100	\$ 3,000.00	1750 ✓
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,552.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 2044 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>repair</i>	1	\$ 2,070.00		
2	REAR BUMPER ADAPTER - LH <i>X</i>	1	\$ 38.00		<i>X 1 2 3</i>
3	REAR BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 67.00		
4	REAR DOOR - LH <i>repair</i>	1	\$ 2,767.00		
5	REAR DOOR OUTER SEAL - LH <i>X nn</i>	1	\$ 161.00		
6	BONDING AGENT <i>X nn</i>	1	\$ 49.00		
7	CLEANING SOLUTION <i>X nn</i>	1	\$ 68.00		
8	APPLICATOR <i>X nn</i>	1	\$ 8.00		
9	REAR DOOR CATCH - LH <i>X nn</i>	1	\$ 94.00		
10	REAR WHEEL HOUSING LINER - LH <i>X nn</i>	1	\$ 240.00		
11	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>X nn</i>	1	\$ 57.00		
12	REAR TYRE RIM - LH <i>repair (polish)</i>	1	\$ 1,166.00		
13	SUNDRIES <i>?</i>	1	\$ 250.00		<i>X 1 2 3</i>
TOTAL SPARE PARTS			: \$ 7,035.00		
TOTAL LABOUR CHARGES			: \$ 6,552.00		
GRAND TOTAL			: \$ 13,587.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : RasuL - Hp 90010068
SURVEYED DATE : 31/05/21 @ 1130
AUTHORISED DATE :
EXCESS COST : 5 days
LIABILITY : EXCESS : TBN
REMARKS : Repair
Resy after repair

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT