



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD Ref: CS/EGI21006290/f3  
 5 TEMASEK BOULEVARD Date: 01/06/2021  
 #04-05 SUNTEC TOWER FIVE  
 SINGAPORE 038985 Code: EGI

1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 6166B	Veh. Inspected	YP 9410K
Policy No.		Coverage (\$)	0.00
Claim No.	CDMCG21000997	Excess (\$)	0.00
Assign From	PAULINE SOH	Assign Date	01/06/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/05/2021	Inspection Date	01/06/2021
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			