



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15318/JONAS LIM GUO JIANN Reg No/Reg Date SMR7746L / 21/01/202 Date In/Mileage 31/05/2021/ 0 Chassis No GF7W0602079 Engine No 4J11BK4228 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	03/06/2021/ 12:13	BLC	442 / CocoLu	11504		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT FENDER ¹ LH, FRT DOOR LH, REAR ¹ DOOR LH				3 X 640			1920 3200.00
E PNT98000 SPRAY PAINT FOR FRT ¹ FENDER LH, FRT ¹ DOOR LH, REAR ¹ DOOR LH				550 X 3			1650 2200.00
E PNT88000 REMOVE & INSTALL FRT DOOR TRIMS, GLASS AND OTHERS							120 300.00
E PNT88000 REMOVE & INSTALL REAR DOOR TRIMS, GLASS AND OTHERS							120 300.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION							80.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							280.00
M SUNDRY Sundry							20.00
X	FENDER,FR LH	/ DD		1.00	622.00	23.00	478.94
X	PANEL ASSY,FR DOOR,LH	/ DD		1.00	982.00	23.00	756.14
M	HINGE,FR DOOR,LWR LH	/ ?		1.00	43.00	23.00	33.11
M	HINGE,FR DOOR,LWR RH	/ ?		1.00	43.00	23.00	33.11
M	REGULATOR,FR DOOR WDO,LH	/ ?		1.00	178.00	23.00	137.06
M	MOTOR,F/DR POWER WDO REG,L	/ ?		1.00	457.00	23.00	351.89
M	BASE,F/DR OUTSIDE HDLE,LH	/ CHT		1.00	135.00	23.00	103.95
M	GASKET,F/DR OUTSIDE HANDLE	/ REC		1.00	6.00	23.00	4.62
X	COVER,F/DR OUTS HANDLE,LH	/ MIS		1.00	50.00	23.00	38.50
M	HANDLE,RR DOOR OUTSIDE,LH	/ X		1.00	93.00	23.00	71.61
M	LATCH,FR DOOR,LH	/ ?		1.00	322.00	23.00	247.94
M	CHECK,FR DOOR	/ ?		1.00	31.00	23.00	23.87
X	PANEL ASSY,RR DOOR,LH	/ DD		1.00	864.00	23.00	665.28
X	TAPE,FR DOOR SASH,LH	/ REC		1.00	42.00	23.00	32.34
X	TAPE,RR DOOR SASH	/ REC		1.00	42.00	23.00	32.34
X	TAPE,RR DOOR SASH	/ REC		1.00	42.00	23.00	32.34

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV15318/JONAS LIM GUO JIANN
31/05/	Reg No/Reg Date	SMR7746L / 21/01/202
	Date In/Mileage	31/05/2021/ 0
	Chassis No	GF7W0602079
	Engine No	4J11BK4228
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	03/06/2021/ 12:13	BLC	442 / Cocolu	11504

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GARNISH,FR DOOR,LH	1.00	190.00	23.00	146.30
M GARNISH,RR DOOR,LH	1.00	164.00	23.00	126.28
M WHEEL,DISC X	1.00	974.00	23.00	749.98

Estimate

Steve (LKK)
3/6/21, 2:00pmw.r. RL
b dy
P/P
My B&L dy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by Date:

	Nett	10,475.60
7% GST on	10475.60	733.29
Total Payable		11,208.89

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.