



Exceptional Journeys

Surveyor : STEVE LKK
Claim : TP CHINA TAIPING
DOA : 29.05.2021
Emailed : 08.06.2021, 1.10pm
Date survey : 03.06.2021

VEHICLE NO : SMR 7746 L
MODEL : MIT OUTLANDER 2.0
WIP : 11504

Material	:	\$	2,905.00
Labour	:	\$	4,488.00
Sub-Total	:	\$	7,393.00
	:		-
Less Excess	:	\$	-
Total	:	\$	7,393.00
GST 7%	:	\$	517.51
Grand Total	:	\$	7,910.51
Finalise By/Date	:		LOI / 08/06/2021

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 6 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 8

☒ TP claim YQ 2549 K

☒ Claim GIA / LTA fee \$7.45

☒ Claim Loss of ☒ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
JONAS LIM GUO JIANN	Cust No/Name KCV15318/JONAS LIM GUO JIANN
BLK 538 HOUGANG STREET 52	Reg No/Reg Date SMR7746L / 21/01/2020
#08-86	Date In/Mileage 31/05/2021/ 14642
SINGAPORE 530538	Chassis/Package GF7W0602079 /DC17P
Contact No Mobile: 96665092	Engine No 4J11BK4228
31/05/2021	Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	08/06/2021/ 11:38	TLC	260 / AiTing	11504		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH FRONT FENDER, LH FRONT DOOR, LH REAR DOOR, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME							✓ 1920.00
E PNT98000 RESPRAY ON LH FRONT FENDER, LH FRONT DOOR, LH REAR DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME							✓ 1650.00
E PNT88000 REMOVE & INSTALL LH FRONT DOOR TRIMS, GLASS, AND OTHER ATTACHMENTS TO NEW PANEL							✓ 120.00
E PNT88000 REMOVE & INSTALL LH REAR DOOR TRIMS, GLASS, AND OTHER ATTACHMENTS TO NEW PANEL							✓ 120.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS							✓ 80.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM							✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE							✓ 280.00
M SUNDRY SUNDRIES							✓ 20.00
M SUNDRY BASE, F/DR OUTSIDE HDLE,LH → Parts							✓ 135.00
M SUNDRY GASKET,F/DR OUTSIDE HANDLE → Parts							✓ 6.00
M SUNDRY W/STRIP, RR DOOR OPNG, FR LH → Supp. (parts)							127.00
X	FENDER,FR LH			1.00	✓ 622.00	00.00	622.00
X	PANEL ASSY,FR DOOR,LH			1.00	✓ 982.00	00.00	982.00
X	COVER,F/DR OUTS HANDLE,LH			1.00	✓ 50.00	00.00	50.00
X	PANEL ASSY,RR DOOR,LH			1.00	✓ 864.00	00.00	864.00
X	TAPE,FR DOOR SASH,LH			1.00	✓ 42.00	00.00	42.00
X	TAPE,RR DOOR SASH			1.00	✓ 42.00	00.00	42.00

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
JONAS LIM GUO JIANN	Cust No/Name KCV15318/JONAS LIM GUO JIANN
BLK 538 HOUGANG STREET 52	Reg No/Reg Date SMR7746L / 21/01/2020
#08-86	Date In/Mileage 31/05/2021/ 14642
SINGAPORE 530538	Chassis/Package GF7W0602079 /DC17P
Contact No Mobile: 96665092	Engine No 4J11BK4228
31/05/2021	Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	08/06/2021/ 11:39	TLC	260 / AiTing	11504		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	TAPE,RR DOOR SASH			1.00	✓ 42.00	00.00	42.00
X	HANDLE,RR DOOR OUTSIDE,LH			1.00	? 93.00	00.00	93.00
X	MOULDING,FR WHEEL ARCH,LH → Supp .			1.00	168.00	00.00	168.00
Z	TEXT						
	TP CLAIM CHINA TAIPING YQ2549K						
	DOA : 29.05.21						
	SURVEYOR STEVE LKK 03.06.21						
	REPAIR 06 DAYS						
Pro Forma							
Guarantee Your Warranty, Maintain with Cycle & Carriage!							

Parts	2,905.00	Nett	7,393.00
Labour	4,120.00	7% GST on	517.51
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	7,910.51
Sundry/Others	368.00		
Total(w/o GST)	7,393.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : CHINA TAIPING


Supplementary Parts For Registration No.: SMR 7746 L

<u>Material</u>		<u>Cost (\$)</u>	
1	W/strip, RR door opng, Fr LH	127.00	/ TN
2	Moulding, Fr wheel arch, LH	168.00	/ neL

Total Taxable		295.00	
7% GST		20.65	
Grand total		<u>315.65</u>	

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



LOI AI TING
SENIOR OFFICER - ADMIN
DID : 6568 45556 / 6568 4501
FAX : 6567 5258 / 6565 1240