



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #03-16 AIG BUILDING SINGAPORE 079120 Contact No 6415 1892	Cust No/Name KCV15318/JONAS LIM GUO JIANN Reg No/Reg Date SMR7746L / 21/01/202 Date In/Mileage 31/05/2021/ 0 Chassis No GF7W0602079 Engine No 4J11BK4228 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

31/05/

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	03/06/2021/ 12:13	BLC	442 / CocoLu	11504			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FRT FENDER LH, FRT DOOR LH, REAR DOOR LH	3 X 640			1920			3200.00
E PNT98000	SPRAY PAINT FOR FRT FENDER LH, FRT DOOR LH, REAR DOOR LH	550 X 3			1650			2200.00
E PNT88000	REMOVE & INSTALL FRT DOOR TRIMS, GLASS AND OTHERS				120			300.00
E PNT88000	REMOVE & INSTALL REAR DOOR TRIMS, GLASS AND OTHERS				120			300.00
M SUNDRY	APPLY SEALANT FOR ACCIDENT PORTION							80.00
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							280.00
M SUNDRY	USING HI-SCAN PRO TEST							20.00
X Sundry					1.00	622.00	23.00	478.94
X FENDER,FR LH					1.00	982.00	23.00	756.14
X PANEL ASSY,FR DOOR,LH					1.00	43.00	23.00	33.11
M HINGE,FR DOOR,LWR LH					1.00	43.00	23.00	33.11
M HINGE,FR DOOR,LWR RH					1.00	178.00	23.00	137.06
M REGULATOR,FR DOOR WDO,LH					1.00	457.00	23.00	351.89
M MOTOR,F/DR POWER WDO REG,L					1.00	135.00	23.00	103.95
M BASE,F/DR OUTSIDE HDLE,LH					1.00	6.00	23.00	4.62
M GASKET,F/DR OUTSIDE HANDLE					1.00	50.00	23.00	38.50
X COVER,F/DR OUTS HANDLE,LH					1.00	93.00	23.00	71.61
M HANDLE,RR DOOR OUTSIDE,LH					1.00	322.00	23.00	247.94
M LATCH,FR DOOR,LH					1.00	31.00	23.00	23.87
M CHECK,FR DOOR					1.00	864.00	23.00	665.28
X PANEL ASSY,RR DOOR,LH					1.00	42.00	23.00	32.34
X TAPE,FR DOOR SASH,LH					1.00	42.00	23.00	32.34
X TAPE,RR DOOR SASH					1.00	42.00	23.00	32.34
X TAPE,RR DOOR SASH								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 31/05/	Cust No/Name KCV15318/JONAS LIM GUO JIANN Reg No/Reg Date SMR7746L / 21/01/202 Date In/Mileage 31/05/2021/ 0 Chassis No GF7W0602079 Engine No 4J11BK4228 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	03/06/2021/ 12:13	BLC	442 / CocoLu	11504			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GARNISH,FR DOOR,LH	✓	X	M/M	1.00	190.00	23.00	146.30
M	GARNISH,RR DOOR,LH	?	X	M/M	1.00	164.00	23.00	126.28
M	WHEEL,DISC	X		M/M	1.00	974.00	23.00	749.98

Estimate

Steve (LKK)
3/6/21, 2.00pm

Mr RL
6 dy
P/P
My B&L dy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by Date:

7% GST on Net 10,475.60 733.29
Total Payable 11,208.89

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.