



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: DANIEL PAY			Ref: CS/ASM21006300/Atce2 Date: 13/10/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJY 2868A		Veh. Inspected	SFA 23H
Policy No.			Coverage (\$)	0.00
Claim No.	S1M03ASI		Excess (\$)	0.00
Assign From	DANIEL PAY		Assign Date	28/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ C180		c.c	1595
Engine No.	HIDDEN		Year of Reg.	2015
Chassis No.	WDD2050402R101636		Colour	BLACK
Odometer	107612 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre	225/50 R17		CONTINENTAL	6 mm
L/H Front Tyre	225/50 R17		CONTINENTAL	6 mm
R/H Rear Tyre	225/50 R17		CONTINENTAL	6 mm
L/H Rear Tyre	225/50 R17		CONTINENTAL	6 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/05/2021		Inspection Date	31/05/2021
Survey held at	FLYING HIGH SPRAY PAINTING BLK 1 KAKI BUKIT AVE 6 #01-29 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	