



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21006305/Aqf3n2 Date: 20/08/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJP 5908X	Veh. Inspected	GZ 665L	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010384/ST	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	01/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ VITO	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDF44760323084110	Colour	BLACK	
Odometer	187443 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/05/2021	Inspection Date	02/06/2021	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	