




PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0440/2021/GW
DATE : 22-May-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120


Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	: MS. CHIN SIWEI
ADDRESS	: 21 CHIM MOH ROAD #10-151 SINGAPORE 270021
TELEPHONE	: HP +65 94892016
TYPE OF CLAIM	: OWN POLICY CLAIMS
POLICY NO	: 721000107
VEHICLE NO	: SMX 7128 P
MODEL CODE	: AUDI Q3 1.4 TFSI
MODEL YEAR	: 19/12/1984
ENGINE NO	: CZDC 18735
CHASSIS NO	: WAUZZZF36M1044875
MILEAGE	: -
DATE IN	: -
ESTIMATED BY	: JOHNNY BOO / ALLAN WU
ACCIDENT DATE	: 27-Apr-21
PLACE OF ACCIDENT	: ALONG CORONATION WALK



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 7128 P

S/N	NATURE OF JOBS	S/N	\$	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PAKING AID REAR LID KICK SENSOR.	S/N	\$	360.00	/
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	1,200.00 500	/
3	TO RESPRAY REAR BUMPER.		\$	1,000.00 550	/
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$	192.00	/
SUB-TOTAL LABOUR CHARGES		:	\$	<u>2,752.00</u>	



PREMIUM AUTOMOBILES

S5 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7128 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>scr x R</i>	1	\$	1,634.00 <i>X</i>	
2	REAR BUMPER FIXING PARTS <i>x su</i>	1	\$	211.00 <i>X</i>	
3	REAR BUMPER SPOILER <i>scr</i>	1	\$	459.00 <i>367.20</i>	
4	REAR BUMPER SPOILER BRACKET <i>? x su</i>	1	\$	48.00 <i>X</i>	
5	REAR BUMPER COVER-CENTER <i>x su</i>	1	\$	97.00 <i>X</i>	
6	REAR LIGHT REFLECTOR-LH <i>scr x su</i>	1	\$	41.00 <i>X</i>	
7	REAR BUMER GUIDE SECTION <i>? x su</i>	1	\$	63.00 <i>X</i>	
8	REAR WHEEL COVER-LH/RH <i>scr</i>	2	\$	536.00 <i>428.80</i>	
9	SUNDRIES <i>? x su</i>		\$	200.00 <i>X</i>	
TOTAL SPARE PARTS			:	\$ 3,289.00	
TOTAL LABOUR CHARGES			:	\$ 2,752.00	
GRAND TOTAL			:	\$ 6,041.00	


ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



*Issue - 4890010018
to 01/06/21 @ 1300hrs
3 days
excess: TBA
Repair before part*

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :
THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT