

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006327/EQF3E2

Date: 09/06/2021

REFERENCE

Insured/Claimant:	SRABANI BHARADWAJ	Policy No:	1900017566		
Date of Loss:	31/05/2021	Nature of Claim:	OD	Claim No:	2954383795SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ7687R	Engine No:	4B40GH0208
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 (A)	Chassis No:	JMAXTGK1WKZ000673
Reg. Date:	20/03/2019 (Man. Year: 2018)	Odometer:	21103 km
Colour:	Red		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	800.00	800.00	0.00	0.00
Nett Amount (S\$)	-800.00	-800.00	0.00	0.00

INSPECTION

Date of Assignment:	02/06/2021	
Date Inspected:	02/06/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	0.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

New Car Prices :	\$134,999.00
Market Value :	\$95,000.00
OMV :	\$26,834.00
PARF Rebate (1) :	\$22,176.00
Quota Premium Paid :	\$33,989.00
COE Rebate (2) :	\$26,496.00
Total Rebate (1) + (2) = :	\$48,672.00

The total amount incurred will be Market Value \$95,000.00 minus Total Rebate \$48,672.00 = \$46,328.00 before excess.

The total amount incurred will be New Car Prices \$134,999.00 minus Total Rebate \$48,672.00 = \$86,327.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >