



Accident Reference & Bus No: E/2445/2021 - SBS8417E

Activated date: Tue 6/1/2021 1:01 PM

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Estimate for

Stock Code	Description	Quantity	Total Material cost(S\$)
30541740	LED INDICATOR LAMP	1	\$100.00

cra ✓

- ☐ Parts cost: \$ 100
- ☐ Contractor Labour cost: \$ 500 +gst
- ☐ Advertisement Cost: \$ 0
- ☐ Repair period: 2 day

-
- ☐ Tow Cost: \$ 0
 - ☐ Overheads: \$ ~~235.20~~