



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--|---------------------------|------------|
| MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | | Ref: CC3/FCI21006329/Kte2 | |
| | | | Date: 02/06/2021 | |
| | | | Code: FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHA 3076L | Veh. Inspected | SHC 5470H |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | D19000835MFSH | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 16/12/2016 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | RENAULT LATITUDE 2.0 | c.c | 1995 |
| | Engine No. | HIDDEN | Year of Reg. | 2014 |
| | Chassis No. | VF1ABL15AUC280955 | Colour | RED |
| | Odometer | 221652 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 215/60 R16 | WEST LAKE | 6 mm |
| | L/H Front Tyre | 215/60 R16 | WEST LAKE | 6 mm |
| | R/H Rear Tyre | 215/60 R16 | WEST LAKE | 6 mm |
| | L/H Rear Tyre | 215/60 R16 | WEST LAKE | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 14/12/2016 | Inspection Date | 16/12/2016 |
| | Survey held at | TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | |
| 5a. Remarks | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | |