

ASS. REG. BY:

REF:

U02/21008338/Kg^{f3}

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. DHOM110137511406

Claims No. _____


Sum Insured: _____ Excess: NIL

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$115K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: EU 564 Yr Regn: 03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A8L c.c. 2995

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 36658 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W4U 7774H 2E No 12384

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: 265/40R20

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A. 21/5/21 D.O.I. 3/6/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

03/06/21 @ 1.42pm revert to Katie by email.

04/06/21 Submit Uneconomical Total Loss Report.

17/06/21 @ 3.31pm Katie informed C/A at \$22058 & the balance will top up by owner.

17/06/21 @ 6.05pm Informed Steven C/A up to \$22K or lower & ex: NIL by email.

repair sum \$22000, 6 days (Red \$24365, 53%)

Date/Time, File Pass to?

04/06/21 Typist

Date/Time, File Return to?

2)

☐ : Prell. Report☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ - RS - \$

Fees

Others

TOTAL

Report Format: OD

Lump Sum / I.D. (\$ repair sum \$22000)

THIAM HENG HUAT PTE LTD

176 Sin Ming Drive

#05-14 Sin Ming AutoCare

Singapore 575721

Phone 8263 6295 (Steven) Fax 6266 2881

United Overseas Insurance Ltd

3 Anson Road, #28-01 Springleaf

Tower Singapore 079909

Date : 02-06-21

Not Authorised

L1 Sup @

Mercury After Pain

Kenarth (LKA) Ex ?

Vehicle No : EU56U
Policy No : DHOM110137511406
Chassis No : WAUZZZ4H2ENO12384
Make/Mode: AUDI A8
DOA : 21-05-21

S/N	Qty	Description	Unit Price	Amount	
1	1pc	FRONT BONNET	<i>Bu</i> \$ 3,400.00	\$ 3,400.00	✓
2	1pc	FRONT RADIATOR GRILLE	<i>Sm</i> \$ 2,550.00	\$ 2,550.00	X
3	1pc	FRONT RADIATOR GRILLER " EMBLEM "	<i>Sm</i> \$ 136.00	\$ 136.00	X
4	1pc	FRONT HEADLAMP LH	<i>Bro</i> \$ 9,350.00	\$ 9,350.00	✓
5	1pc	FRONT HEADLAMP BRACKET LH	<i>CM</i> \$ 236.00	\$ 236.00	✓
6	1pc	FRONT BUMPER	<i>Bu</i> \$ 2,720.00	\$ 2,720.00	✓
7	1pc	FRONT BUMPER TOWING COVER	<i>Sm</i> \$ 85.00	\$ 85.00	X
8	1pc	FRONT BUMPER RETANNAL LH	<i>CM</i> \$ 59.50	\$ 59.50	✓
9	1pc	FRONT BUMPER LOWER GARNISH LH	<i>Bu</i> \$ 425.00	\$ 425.00	✓
10	1pc	FRONT BUMPER NOZZLE COVER LH	<i>Sm</i> \$ 59.50	\$ 59.50	X
11	1pc	FRONT BUMPER NOZZLE LEVER LH	<i>Sm</i> \$ 187.00	\$ 187.00	X
12	1pc	FRONT BUMPER NOZZLE WASHER JET LH	\$ 234.00	\$ 234.00	?
13	1pc	FRONT BUMPER REFORCEMENT	<i>R</i> \$ 935.00	\$ 935.00	X
14	1pc	FRONT BUMPER SPONCE	<i>Sm</i> \$ 119.00	\$ 119.00	X
15	1pc	FRONT FENDER LH	<i>Bu</i> \$ 1,360.00	\$ 1,360.00	✓
16	1pc	FRONT SUPPORT PANAL	<i>CM</i> \$ 935.00	\$ 935.00	✓
18	1pc	FRONT KNUCKER ARM LH	<i>Sm</i> \$ 1,360.00	\$ 1,360.00	X
19	1pc	FRONT WHEEL HUP LH	<i>Sm</i> \$ 510.00	\$ 510.00	X
20	1pc	FRONT WHEEL BEARING LH	<i>Na</i> \$ 612.00	\$ 612.00	X
21	1pc	FRONT LOWER ARM LH	<i>Sm</i> \$ 544.00	\$ 544.00	X
22	1pc	FRONT ABSORBER LH	<i>Sm</i> \$ 3,910.00	\$ 3,910.00	X
23	1pc	FRONT TIE ROD LH	<i>Sm</i> \$ 238.00	\$ 238.00	X
24	1pc	FRONT TIE ROD END LH	<i>Sm</i> \$ 153.00	\$ 153.00	X
25	1pc	FRONT TORSION BAR LINK	<i>Sm</i> \$ 986.00	\$ 986.00	X
26	1pc	FRONT DRIVER SHAFT	<i>R</i> \$ 2,890.00	\$ 2,890.00	X
27	1pc	FRONT FENDER INNER SHIELD	<i>T</i> \$ 238.00	\$ 238.00	✓
28	1pc	FRONT FENDER INNER SHIELD	<i>Sm</i> \$ 204.00	\$ 204.00	X
29	1pc	FRONT SENSOR LH	\$ 00	\$ 00	?
30	1pc	FRONT SENSOR CORNER LH	<i>CM</i> \$	\$	✓
31	1pc	FRONT SENSOR WIRE HARNES	<i>Na</i> \$	\$	✓
32	1pc	FRONT INTERCOOLER PROTECT	\$	\$	✓
33	1pc	FRONT INTERCOOLER INNER AIR	\$	\$	✓

THIAM HENG HUAT PTE LTD

176 Sin Ming Drive

#05-14 Sin Ming AutoCare

Singapore 575721

Phone 8263 6295 (Steven) Fax 6266 2881

United Overseas Insurance Ltd
3 Anson Road, #28-01 Springleaf
Tower Singapore 079909

Date : 02-06-21

Vehicle No : EU56U
Policy No : DHOM110137511406
Chassis No : WAUZZZ4H2ENO12384
Make/Model: AUDI A8
DOA : 21-05-21

Labour Charges

	Balance b/d	\$ 36,445.00	
2 To rectify front bumper sensor harness wiring system		200.00	801
3 To knocking remove n refix front bonnet , support panel , fender lh , front bumper		4,000.00	801
4 To remove & install replace radiator , cooling system & all repair , including pressure test , bleed cooling system & check leaks necessary part to facilitate		2,000.00	X
5 To vacuum system and refill gas		200.00	1001
6 To check for function and alignment headlamp lh & rh		200.00	301
7 To respray front accident portion front bonnet , front bumper , front fender lh		3,000.00	1001
8 To towing accident vehicle to workshop		200.00	1301
9 To wheel alignment		120.00	X
Total		\$ 47,165.00	46365
	7% GST	3,301.55	
Grand Total		<u>\$ 50,466.55</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/05/2021 16:44 (SGT)
Date of Accident	21/05/2021 17:45 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	100 PECK SEAH STREET
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number EU56U

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WEE WEI CHI
NRIC No	SXXXX459D
Email Address	davideu1718@gmail.com
Mobile Phone No	(Phone) +65-65338651
Alternative Phone No	+65-96691416

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A8L 4.0 TFSI QU (PI)
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	3993

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DHOM110137511406
Cover Note Number	-

DRIVER

Name of Driver	EU YEE TAT DAVID
NRIC No	SXXXX387Z

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

Vehicle Details

Vehicle No.:

459D

Vehicle to be Exported:

EU56U

Intended Deregistration Date:

No

Vehicle Make:

31 May 2021

Vehicle Model:

AUDI

Primary Colour:

A8L 4.0 TFSI QU (PI)

Manufacturing Year:

White

Engine No.:

2014

Chassis No.:

CTG001424

Maximum Power Output:

WAUZZZ4H2EN012384

Open Market Value:

320.0 kW (429 bhp)

Original Registration Date:

\$95,844.00

First Registration Date:

31 Mar 2014

Transfer Count:

31 Mar 2014

Actual ARF Paid:

1

Intended PARF Rebate Details

PARF Eligibility:

\$144,520.00

PARF Eligibility Expiry Date:

Yes

PARF Rebate Amount:

30 Mar 2024

Intended COE Rebate Details

COE Expiry Date:

\$86,712.00

COE Category:

30 Mar 2024

COE Period(Years):

E - Open Category

QP Paid:

10

COE Rebate Amount:

\$82,000.00

Total Rebate Amount:

\$22,846.00

\$109,558.00

The information contained herein is correct as at 31 May 2021

OK

THIAM HENG HUAT PTE LTD

176 Sin Ming Drive

#05-14 Sin Ming AutoCare

Singapore 575721

Phone 8263 6295 (Steven) Fax 6266 2881

United Overseas Insurance Ltd

3 Anson Road, #28-01 Springleaf

Tower Singapore 079909

Date : 02-06-21

Vehicle No : EU56U

Policy No : DHOM110137511406

Chassis No : WAUZZZ4H2ENO12384

Make/Mode: AUDI A8

DOA : 21-05-21

*Not Authored**L/Sup @**Meeting After Pains**Kennerth CLKK Ex ?*

S/N	Qty	Description		Unit Price	Amount	
1	1pc	FRONT BONNET	<i>Bu</i>	\$ 3,400.00	\$ 3,400.00	✓
2	1pc	FRONT RADIATOR GRILLE	<i>Sm</i>	\$ 2,550.00	\$ 2,550.00	X
3	1pc	FRONT RADIATOR GRILLER " EMBLEM "	<i>Sm</i>	\$ 136.00	\$ 136.00	X
4	1pc	FRONT HEADLAMP LH	<i>Bu</i>	\$ 9,350.00	\$ 9,350.00	✓
5	1pc	FRONT HEADLAMP BRACKET LH	<i>CM</i>	\$ 236.00	\$ 236.00	✓
6	1pc	FRONT BUMPER	<i>Bu</i>	\$ 2,720.00	\$ 2,720.00	✓
7	1pc	FRONT BUMPER TOWING COVER	<i>Sm</i>	\$ 85.00	\$ 85.00	X
8	1pc	FRONT BUMPER RETANNAL LH	<i>CM</i>	\$ 59.50	\$ 59.50	✓
9	1pc	FRONT BUMPER LOWER GARNISH LH	<i>Bu</i>	\$ 425.00	\$ 425.00	✓
10	1pc	FRONT BUMPER NOZZLE COVER LH	<i>Sm</i>	\$ 59.50	\$ 59.50	X
11	1pc	FRONT BUMPER NOZZLE LEVER LH	<i>Sm</i>	\$ 187.00	\$ 187.00	X
12	1pc	FRONT BUMPER NOZZLE WASHER JET LH		\$ 234.00	\$ 234.00	?
13	1pc	FRONT BUMPER REFORCEMENT	<i>R</i>	\$ 935.00	\$ 935.00	X
14	1pc	FRONT BUMPER SPONCE	<i>Sm</i>	\$ 119.00	\$ 119.00	X
15	1pc	FRONT FENDER LH	<i>Bu</i>	\$ 1,360.00	\$ 1,360.00	✓
16	1pc	FRONT SUPPORT PANAL	<i>CM</i>	\$ 935.00	\$ 935.00	✓
18	1pc	FRONT KNUCKER ARM LH	<i>Sm</i>	\$ 1,360.00	\$ 1,360.00	X
19	1pc	FRONT WHEEL HUP LH	<i>Sm</i>	\$ 510.00	\$ 510.00	X
20	1pc	FRONT WHEEL BEARING LH	<i>na</i>	\$ 612.00	\$ 612.00	X
21	1pc	FRONT LOWER ARM LH	<i>Sm</i>	\$ 544.00	\$ 544.00	X
22	1pc	FRONT ABSORBER LH	<i>Sm</i>	\$ 3,910.00	\$ 3,910.00	X
23	1pc	FRONT TIE ROD LH	<i>Sm</i>	\$ 238.00	\$ 238.00	X
24	1pc	FRONT TIE ROD END LH	<i>Sm</i>	\$ 153.00	\$ 153.00	X
25	1pc	FRONT TORSION BAR LINK	<i>Sm</i>	\$ 986.00	\$ 986.00	X
26	1pc	FRONT DRIVER SHAFT	<i>R</i>	\$ 2,890.00	\$ 2,890.00	X
27	1pc	FRONT FENDER INNER SHIELD FR	<i>Tn</i>	\$ 238.00	\$ 238.00	✓
28	1pc	FRONT FENDER INNER SHIELD RR	<i>Sm</i>	\$ 204.00	\$ 204.00	X
29	1pc	FRONT SENSOR LH		\$ 221.00	\$ 221.00	?
30	1pc	FRONT SENSOR CORNER LH	<i>Shon</i>	\$ 221.00	\$ 221.00	✓
31	1pc	FRONT SENSOR WIRE HARNESS CABLE ASSY	<i>Tn</i>	\$ 1,125.00	\$ 1,125.00	✓
32	1pc	FRONT INTERCOOLER PROTECTOR BAR LH	<i>Bu</i>	\$ 204.00	\$ 204.00	✓
33	1pc	FRONT INTERCOOLER INNER AIR DUCT LH		\$ 238.00	\$ 238.00	?
Balance c/f					\$ 36,445.00	

58