



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21006338/Kqf3e2	
			Date: 21/10/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	EU 56U
	Policy No.	DHOM110137511406	Coverage (\$)	0.00
	Claim No.	M11D13062106	Excess (\$)	0.00
	Assign From	KATIE LEE	Assign Date	02/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A8L (A)	c.c	2995
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WAUZZZ4H2EN012384	Colour	WHITE
	Odometer	36658 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	265/40 R20	PIRELLI	8 mm
	L/H Front Tyre	265/40 R20	PIRELLI	8 mm
	R/H Rear Tyre	265/40 R20	PIRELLI	8 mm
	L/H Rear Tyre	265/40 R20	PIRELLI	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/05/2021	Inspection Date	03/06/2021
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
5a. Remarks				
	A)THE MARKET VALUE IS S\$115,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	