

EURO SUCCESS SERV PTE. LTD

1 KAKIT BUKIT AVE 6, #02-03 SINGAPORE 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (Ah Huat)

Vehicle No: SJY6555B

Model: SUBARU FORESTER 2.0X

instal not Authorized
the
3/6/11
2/s + 8200/
8 days.

QTY	LIST ITEMS		AMOUNT	
1	FRONT DOOR LH	Body 120	\$ 1,800.00	✓
1	FRONT DOOR INNER HANDLE	svc.	\$ 150.00	X
1	FRONT DOOR INNER LOCK LH	shanked / 1/4" 299	\$ 350.00	✓
2	FRONT DOOR HINGES LH @70.00	1/1	\$ 140.00	X
1	FRONT DOOR PROTECTOR LH	NP	\$ 350.00	X
1	FRONT DOOR INNER TRIM LH	del / torn	\$ 900.00	X
1	FRONT DOOR INNER TRIM RUBBER LH	del 132	\$ 135.00	✓
1	FRONT DOOR REGULATOR LH	but / 1/4" 320	\$ 600.00	✓
1	FRONT DOOR OUTER HANDLE LH	scr 250	\$ 350.00	✓
1	FRONT DOOR POWER WINDOW MOTOR LH	clw regulator	\$ 750.00	X
1	FRONT DOOR POWER WINDOW SWITCH LH	1/1	\$ 350.00	X
1	FRONT DOOR POWER WINDOW REGULATOR LH	Repeal	\$ 550.00	X
1	FRONT DOOR STEP GARNISH LH	1/1	\$ 280.00	X
1	FRONT DOOR WEATHER STRIP LH	Repeal	\$ 220.00	X
1	FRONT DOOR LOWER RUBBER SEAL LH	1/1	\$ 65.00	X
1	FRONT DOOR FRAME BLACK STICKER	del 68	\$ 70.00	✓
1	FRONT DOOR FRAME WEATHER STRIP LH	1/1	\$ 200.00	X
1	FRONT DOOR AUDIO SPEAKER LH	1/1	\$ 400.00	X
1	FRONT SIDE MIRROR	1/1	\$ 750.00	X
1	FRONT CENTER LOCK	NS	\$ 220.00	X
1	ROCKER PANEL LH	R	\$ 1,300.00	X
1	ROCKER PANEL LOWER GARNISH LH	1/1	\$ 490.00	X
1	TAIL LAMP LH	1/1	\$ 472.00	X
1	REAR FENDER LH	Body 120	\$ 1,330.00	✓
1	REAR FENDER INNER TRIM LH	del / torn 288	\$ 998.00	✓
1	REAR FENDER ARCH SEAL LH	NS	\$ 185.00	✓
1	REAR FENDER COWLING LH	1/1	\$ 151.80	✓
1	CENTER PILLER INNER TRIM LH	1/1	\$ 359.85	X
1	REAR BUMPER	D.S 602.00	\$ 1,215.50	✓
2	REAR BUMPER SIDE RETAINER @75	NS but 45	\$ 150.00	1/2
2	REAR BUMPER PDC SENSOR @352.75	1/1	\$ 705.50	X
1	REAR BUMPER DIFFUSER	1/1	\$ 885.23	X
2	REAR BUMPER LOWER BRACKET @45.50	1/1	\$ 91.00	X
1	REAR BUMPER REINFORCEMENT	1/1	\$ 1,020.84	X
1	REAR BUMPER INNER TOP BRACKET	1/1	\$ 323.56	X
1	REAR BUMPER DIFFUSER INNER GARNISH	1/1	\$ 334.69	X
1	REAR BUMPER LOWER EXHAUST GARNISH	1/1	\$ 150.58	X
1	REAR WHEEL RIM LH	but / warped	\$ 1,650.50	650 5/11
1	REAR SHOCK ABSORBER LH	1/1	\$ 655.25	✓
1	REAR WHEEL HUB LH	but 320	\$ 332.50	✓
1	REAR LOWER ARM LH	but 269	\$ 430.68	✓
1	REAR LOWER ARM ADJUSTABLE ARM LH	but 250	\$ 325.00	✓
1	REAR SWING ARM LH	1/1	\$ 485.00	X
1	REAR KNUCKLE ARM	but 385	\$ 700.00	✓
1	REAR UPPER ARM LH	1/1 248	\$ 384.00	✓
1	REAR DRIVESHAFT	1/1	\$ 1,050.00	X
1	EXHAUST	1/1	\$ 1,850.00	X
1	EXHAUST PIPE	1/1	\$ 895.00	X
1	EXHAUST BOX	1/1	\$ 2,500.00	X
1	EXHAUST INSULATOR	1/1	\$ 1,855.00	X
1	EXHAUST CHROME PLATE LH	1/1	\$ 380.54	X

1	REAR END PANEL	11		\$	1,450.85	X
1	REAR END PANEL INNER BOARD	11		\$	785.98	X
1	REAR KICK SENSOR	11		\$	322.16	X
1	REAR DOOR LH	3-1500	915	\$	1,845.00	/
1	REAR DOOR INNER HANDLE	11		\$	135.00	X
1	REAR DOOR INNER LOCK LH	shut/ym	299	\$	321.00	/
2	REAR DOOR HINGES LH @68.00	sent		\$	136.00	/
1	REAR DOOR PROTECTOR LH	NS		\$	322.00	X
1	REAR DOOR INNER TRIM LH	be/70-1	520	\$	845.00	/
1	REAR DOOR INNER TRIM RUBBER LH	ner	130	\$	142.00	/
1	REAR DOOR REGULATOR LH	sent/ym	305	\$	612.00	/
1	REAR DOOR OUTER HANDLE LH	11		\$	351.00	X
1	REAR DOOR POWER WINDOW MOTOR LH	11		\$	712.00	X
1	REAR DOOR POWER WINDOW SWITCH LH	11		\$	365.00	X
1	REAR DOOR POWER WINDOW REGULATOR LH	regul		\$	589.00	X
1	REAR DOOR STEP GARNISH LH	11		\$	298.00	X
1	REAR DOOR WEATHER STRIP LH	regul		\$	212.00	X
1	REAR DOOR LOWER RUBBER SEAL LH	11		\$	68.00	X
1	REAR DOOR FRAME BLACK STICKER LH	11		\$	68.00	✓
1	REAR DOOR FRAME WEATHER STRIP LH	11		\$	193.00	X
1	REAR DOOR AUDIO SPEAKER LH	11		\$	389.00	X
1	REAR CENTER LOCK	NS		\$	300.00	X
1	CROSS MEMBER	sent/ym	250	\$	\$2,385.95	/
1	FOUR REAR GEAR BOX	11		\$	\$1,985.58	X
				Total Price	\$47,120.54	
				Less 20%	\$9,424.11	
				Sub Total Price	\$37,696.43	

DESCRIPTION			TOTAL \$/NETT
10 FRONT DOOR TRIM BOARD CLIP @6.50	11		\$ 65.00 40
10 ROCKER PANEL LOWER GARNISH CLIPS @6.50	11		\$ 65.00 X
8 FRONT FENDER COWLING CLIPS @6.50	11		\$ 52.00 X
8 REAR BUMPER CLIP @6.50	11		\$ 52.00 40
8 REAR DOOR TRIM BOARD CLIP @6.50	11		\$ 52.00 40
10 REAR FENDER INNER TRIM CLIP @6.50	11		\$ 65.00 X
1 REAR SPORTS RIM LH	repal		\$ 800.00 X
1 REAR WHEEL TYRE RH	put/ym	LP 250	\$ 420.00 602 150
TOTAL			\$ 1,571.00

LABOUR CHARGES		PRICE
TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK		\$ 1,800.00 800
TO SPRAY PAINT		\$ 1,500.00 1000
TUFF COAT		\$ 200.00 900
WIRING, BULB CHECKING		\$ 60.00 20
REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR		\$ 300.00 100
TO REMOVE & RE-INSTALL DASHBOARD & SPEAKERS & GARNISH AND BOARD TO ASSIST REPAIR	11	\$ 450.00 X
TO TRANSFER & REMOVE FRONT & REAR LH DOORS TO ASSIST REPAIR		\$ 300.00 120
REMOVE AND REFIT REAR UNDERCARRIAGE		\$ 680.00 250
CONDUCT FULL WHEEL ALIGNMENT		\$ 120.00 60
REMOVE & REINSTALL REAR WINDOW GLASS		\$ 120.00 80
CONDUCT WATER LEAKAGE TEST	11	\$ 120.00 X
TOTAL		\$ 3,860.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$43,127.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-9510-80
202
P-7640-64
S.N-920
L-2520