

ASS. REC. BY: TGLim

REF:

CS/CT121006366/Bgc

Shiau Chan

## ASSIGNMENT

From: \_\_\_\_\_ Date: 3/6/2021

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 78554

at Workshop m/s Bifrost Auto

of 8 Kati Bt Ave 4 Premier #01-49

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. SNM21D203127/C2


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 119,000/2

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMJ 78554 Yr Regn: 6/3/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: BMW 428i Conv. M Sport C.C. 1997

Colour Grey A/C: Insured / Std / NI / NA

Sp. Reading 147522 T/Radio: Insured / Std / NI / NA

Eng/No: A 3481022 N20B20A

C/No: WBA3V32010P766241

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 225/45/18

R: 255/40/18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 1/6/2021 D.O.I. 3/6/2021

Survey held at Bifrost

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: 8,000/2 - 9,000/2 before amendment if any.
	* W/s to provide invoice of part or repair before price is added to total to be amended. - Provided on 18/6/2021 TGLim 18/6/2021
22/06/21@10.47am	revised to lene Tay by email.
	COR recommended is L/S \$ 10,650/2 TGLim 18/6/2021
	MV 119,000/2 TGLim 18/6/2021
	PV 64,712/2 TGLim 18/6/2021
	NV 54,287/2 TGLim 18/6/2021

22/06/21@12.08pm Mr Lim re-finalised with Suanne LS \$10350, 9 days. (Red \$16925.73, 62%)

Date/Time, File Pass to?

Preli. Report

1) 28/06 Typist

Final Report

Date/Time, File Return to?

2)

Rep. Format: MER-TP

Lump Sum / R.E. 10350

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$ )

Interview (\$ )

Tech. Invs (\$ )

Week-end (\$ )

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL



TGLim Min  
3/6/2021  
1320 hrs

Resurvey  
TGLim Min  
3/6/2021  
1500 hrs

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No: **SMJ7855Y**  
Model and make: **BMW 428i**  
Chassis No: **WBA3V32010P766241**

**Qty Spare Parts**

**List price (\$)**

1	Rear bumper	\$ 1,175.32	<sup>2015</sup> 1,419.20	BR✓
1	Rear bumper centre bracket	\$ 55.75	83.75	BR✓
1	Rear bumper lower garnish	\$ 121.00	252.20	BR✓
1	Rear bumper RH centre moulding retainer	\$	✓ 15.55	} NEC✓
1	Rear bumper LH centre moulding retainer	\$	✓ 15.55	
1	Rear bumper inner frame bracket	\$ 32.10	74.75	BR✓
1	Rear bumper reinforcement	\$ 412.00	517.38	BT✓
1	Rear bumper RH corner reverse sensor	\$ 200.00	284.50	} SC✓
1	Rear bumper RH reverse sensor	\$ 200.00	284.50	
1	Rear bumper LH reverse sensor	\$ 200.00	284.50	
1	Rear bumper LH corner reverse sensor	\$ 200.00	284.50	
4	Rear bumper reverse sensor O-rings	\$	✓ 13.00	NECV
4	Rear bumper reverse sensor brackets	\$	149.20	NNX
1	Rear bumper reverse sensor wire harness	\$	317.30	NAX
1	Rear bumper RH side bracket	\$ 32.10	58.75	} NEC✓
1	Rear bumper LH side bracket	\$ 32.10	58.75	
1	Rear bumper RH reflector	\$ 35.20	112.06	} BR✓
1	Rear bumper LH reflector	\$ 35.20	112.06	
1	Rear bumper tow cover	\$ 30.40	35.60	BR✓
1	End panel	\$	206.40	DDXR
1	End panel antenna sensor	\$	110.50	NDX
1	End panel inner garnish	\$ 77.00	163.40	BR✓
1	Exhaust silencer aluminium heat shield	\$	✓ 80.75	BT✓
1	Exhaust silencer with chrome finishers	\$ 948.60	1,096.80	CuTV
1	Exhaust silencer gasket	\$	✓ 45.30	NECV
1	Bootlid	\$ 1,179.80	1,605.30	DD✓
1	Bootlid RH lamp	\$ 280.27	554.05	} BR✓
1	Bootlid LH lamp	\$ 290.27	554.05	
1	Bootlid third brake lamp	\$ 238.10	284.00	BR✓
1	Bootlid centre emblem	\$	✓ 67.80	} NEC✓
1	Bootlid "428i" emblem	\$	✓ 65.40	
1	Bootlid RH number plate lamp	\$	68.00	} NDX
1	Bootlid LH number plate lamp	\$	68.00	
1	Bootlid reverse camera	\$	631.50	NDX
1	Bootlid lock	\$ 101.17	186.00	} JMV
1	Bootlid lock catch	\$	54.07	NDX
1	Bootlid weatherstrip	\$	184.90	NDX
1	Bootlid smart opener control unit	\$	✓ 450.39	SC✓



\* Please provide invoice of part or repair before price is added to total to be amended

1	Bootlid smart opener sensor strip	\$	55.90	NDX
1	Bootlid hard top convertible drive motor	\$	2,634.10	JM ✓
1	Bootlid hard top convertible assy	\$	8,703.50	NDX
1	Bootlid hard top side rubber seal	\$	385.90	NDX
1	Bootlid hard top RH lock	\$	133.20	JM ✓
1	Bootlid hard top LH lock	\$	133.20	JM ✓
2	Rear fender LH / RH	\$	1,898.00	DDV ✓

To provide invoice before add \*

Invoice provided on 18/6/2021 ✓

LH R RH DDV ✓

@ 5%

11,309.02

565.45

10,743.57

-5%

\$ 25,293.51  
\$ 1,264.67  
\$ 24,028.84

### Qty Spare Parts

### Special Nett (\$)

1 set	Rear bumper clips	\$	30.00	100.00 ✓
1	End panel sealant	\$		80.00 NNX
1	Bootlid sealant	\$		80.00 NNX
1	Bootlid windscreen glass sealant	\$		100.00 } NNX
1	Bootlid windscreen glass inner seal	\$		80.00 }

### Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$	700.00	1,000.00 ✓
Spray painting on affected panels	\$		1,000.00 ✓
Check wiring and lighting system	\$	50.00	120.00 ✓
Apply rust coating on affected areas	\$		100.00 ✓
Reset and diagnose electronic control unit and fault code	\$	120.00	350.00 ✓
Remove and replace exhaust silencer and heat shield	\$	150.00	320.00 ✓
Remove and replace rear inner trim, boards, seats, roof lining and garnish to assist repairs	\$	180.00	450.00 ✓
Remove and replace rear bumper reverse sensors and wire harness	\$	60.00	180.00 ✓
Remove and reinstall bootlid hard top convertible windscreen glass	\$		240.00 NNX
Remove and replace bootlid hard top convertible assy, motors, lock, sensors and all attachments to assist repairs	\$	300.00	850.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Lump sum repair  
Repair days 9

\* L/S 10,650.00

TRU in Min  
18/6/2021

	\$	2560.00
	\$	27,275.73
Parts		10,743.57
SN		30.00
Labour		2560.00
		13,333.57
@ 20%		2666.71
		10666.86





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	02/06/2021 16:25 (SGT)
Date of Accident	01/06/2021 15:40 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	REPUBLIC BLVD EXITING TO OPHIR ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ7855Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN PENG TONG PETER
NRIC No	SXXXX347F
Email Address	doreentan92@gmail.com
Mobile Phone No	(Phone) +65-96349712
Alternative Phone No	+65-96349712

### VEHICLE PARTICULARS

Manufacturer	BMW
Model	428i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1997

### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

### DRIVER

Name of Driver	DOREEN TAN SIEW LAI
NRIC No	SXXXX813A

Date Of Birth	03/09/1957
Occupation	Indoor
Date Of Driving Pass	13/12/1982
Driving experience	38 YEARS AND 6 MONTHS
Gender	Female
Mobile Number	(Phone) +65-93656275
Alt. Phone Number	-
Email Address	doreentan92@gmail.com
Address	33 MANGIS ROAD #05-13 SPORE 424968
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9789D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-



Postcode -  
Insurance Company Name -  
Nature Of Damage -  
Details of property damaged in accident -  
No. Of Passenger (Including Driver) -

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	DOREEN TAN SIEW LAI
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMJ7855Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

# SKETCH PLAN

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan





Describe Circumstances of the Accident

I was travelling at the slip road of Republic Blvd.  
 I was behind the stop line giving way to cars at the  
 major road. Out of sudden, I felt a great impact from  
 my vehicle rear portion. When I got down, I saw vehicle  
 (B) collided onto me.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

Driver's Signature (if driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	347F
Vehicle Details	
Vehicle No.:	SMJ7855Y
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jun 2021
Vehicle Make:	B.M.W.
Vehicle Model:	428i CONVERTIBLE M SPORT A/T LED NAV HUD
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	A3481022N20B20A
Chassis No.:	WBA3V32010P766241
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$51,111.00
Original Registration Date:	06 Mar 2015
First Registration Date:	06 Mar 2015
Transfer Count:	1
Actual ARF Paid:	\$59,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Mar 2025
PARF Rebate Amount:	\$38,350.00
Intended COE Rebate Details	
COE Expiry Date:	05 Mar 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$26,362.00
<b>Total Rebate Amount:</b>	<b>\$64,712.00</b>

The information contained herein is correct as at 15 Jun 2021

OK

MV 119,000/2

PV 64,712/2

NV 54,287/2

Tell me



## Need Items for Your Car?

We have thousands of car parts &amp; accessories to explore.

The best online platform to sell and buy car parts &amp; accessories - Marketplace

## Post an Advertisement

Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

2019 Lamborghini Huracan LP580-2 At \$758888.

Cheapest, 1 Owner, Super Low  
Mileage 3200km, Under Agent  
Warranty.  
Direct Owner StarAd

**PRIME MOTOR & LEASING**

(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Reg. Date

20 results/page

8 vehicles

BMW 428i

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	BMW 428i	Any	Any	2015	Any	Any	Any	All
	<b>BMW 4 Series 428i Convertible M-Sport</b>	<b>\$132,800</b>	<b>\$21,650 /yr</b>	<b>28-Sep-2015</b>	1,997 cc	98,730 km	Sports	Available
Equipped With Bastuck Quad Dual Exhaust, Well Maintained By Owner, Servicing Done Up By Owner, Wear & Tear Done Up For Smooth & Reliable Drive, Weekly Washed & Groomed, Interior Well Maintained, A Beauty With White Matt Gloss Finishing, In-House...								
Posted: 22-May-2021 Tags: 2015 BMW 428i, BMW 428i, BMW, 428i								
	<b>BMW 4 Series 428i Gran Coupe M-Sport Sunroof</b>	-	N.A	28-Sep-2015	1,997 cc	-	Luxury	SOLD
The BMW 4 Series Gran Coupe Looks Good, Drives Even Better And Has A Surprisingly Roomy Boot. It Is Just As Good To Drive As The Two-door Coupe But You Get Extra Practicality As A Bonus! Maintained By PML Over The Years, Extensive Preventive Wear An...								
Pang's Motor Trading Pte Ltd								
Posted: 17-May-2021 Tags: 2015 BMW 428i, BMW 428i, BMW, 428i								
	<b>BMW 4 Series 428i Coupe</b>	<b>\$120,800</b>	<b>\$20,770 /yr</b>	19-Aug-2015	1,997 cc	78,000 km	Sports	Available
Options To Respray Of Your Choice! Brand New Body Wrap, New Double Tone Catchy Blue Gold, Full M Body Kit, LTA Approved Bastuck Exhaust! Full Loan Available At \$2400 Plus Monthly, Vehicle Checked By In House Workshop. Bank Loan And In House Loan...								
Precise Auto Trading Pte Ltd								
Posted: 08-Jun-2021 Tags: 2015 BMW 428i, BMW 428i, BMW, 428i								
	<b>BMW 4 Series 428i Gran Coupe Luxury</b>	-	N.A	07-Jul-2015	1,997 cc	-	Luxury	SOLD
Pristine Condition! PML Unit, All Wear And Tear Parts Changed! 100% Loan Available With Low-Interest Rate From 1.88% P.A! 1 To 1 Exchange Without Cash Top-Up! Comprehensive In House 2 Years Warranty And Servicing Package! New 2k Metallic Paint And N...								
Posted: 01-May-2021 Tags: 2015 BMW 428i, BMW 428i, BMW, 428i								
	<b>Merlin Motor &amp; Engineering Works - Specialist for Bmw Car repair, servicing &amp; maintenance</b>							
Established in 1980s, Merlin Motor Works is a Singapore-based company that provides excellent automotive solutions.								
More Info about this shop								
	<b>BMW 4 Series 428i Gran Coupe Sunroof</b>	<b>\$104,800</b>	<b>\$19,920 /yr</b>	25-Jun-2015	1,997 cc	41,118 km	Luxury	Available
PML Unit, 1 Owner, Genuine Low Mileage Done, Excellent Condition, Easy And Flexible Loan Available, Call Our Friendly Sales Consultant For Viewing Today!								
Car Lingual								
Posted: 08-Jun-2021 Tags: 2015 BMW 428i, BMW 428i, BMW, 428i								
	<b>BMW 4 Series 428i Coupe Sunroof</b>	<b>\$102,800</b>	<b>\$20,470 /yr</b>	13-Mar-2015	1,997 cc	58,000 km	Sports	Available
2 Owners And Agent Car, Amazing Conditions With Super Low Mileage Done, Fully Stock Conditions, Rare Grey Color With Red Leather Seat, Car Fully Sheltered Home And Office. See To Believe.								
Posted: 03-Jun-2021 Tags: 2015 BMW 428i, BMW 428i, BMW, 428i								
	<b>BMW 4 Series 428i Gran Coupe Luxury</b>	<b>\$99,988</b>	<b>\$19,720 /yr</b>	11-Feb-2015	1,997 cc	78,000 km	Luxury	Available