

## Veron Chen (LKKAUTO)

---

**From:** Naz (LKKAUTO)  
**Sent:** Friday, 18 June 2021 1:49 PM  
**To:** Sim, Priscilla-LK  
**Cc:** Bryan Ang (LKKAUTO); Veron Chen (LKKAUTO); SUR  
**Subject:** Re: YP 4939K Fire Cse  
**Attachments:** YP 4939K FIRE INVESTIGATION REPORT.pdf

Dear Ms Sim,

Attached herewith is the Fire Investigation Report.

Thank you.

Best Regards,

**Naz** | Technical Investigator

### LKK Auto Consultants

Phone: 6841-2157 | Email: [Naz@lkkauto.com](mailto:Naz@lkkauto.com) | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Sim, Priscilla-LK <Priscilla-LK.Sim@aig.com>  
**Sent:** Wednesday, 9 June 2021 1:18 PM  
**To:** Naz (LKKAUTO) <Naz@lkkauto.com>  
**Cc:** Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: YP 4939K Fire Cse

Hi Naz

Thank you for updates.

Kindly expedite as owner / insurance agent is pressing AIG for status as affecting their business.

In the meantime, can advise pertaining repair adjustment / economical to repair ?

Priscilla Sim LK  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

AIG Building 78 Shenton Way, Level 10  
Singapore 079120

Tel +(65) 6419 1755  
[priscilla-lk.sim@aig.com](mailto:priscilla-lk.sim@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Naz (LKKAUTO) <Naz@lkkauto.com>  
**Sent:** Monday, June 7, 2021 7:37 PM  
**To:** Sim, Priscilla-LK <Priscilla-LK.Sim@aig.com>  
**Cc:** Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** [EXTERNAL] YP 4939K Fire Cse

This message is from an external sender; be cautious with links and attachments.

Dear Ms Sim,

I have inspected the Insured Vehicle and from my preliminary investigations, the source of fire seems to be electrical, more specifically, from the fuel pump wiring harness. I will contact the insured driver to get more info from him as his GIA Report is very vague. I will also find out if this vehicle has had any manufacturer recalls. As such, I will require more time to conduct the ground work. I will update you accordingly.

Thank you.

Best Regards,  
**Naz** | Technical Investigator  
**LKK Auto Consultants**  
Phone: 6841-2157 | Email: [Naz@lkkauto.com](mailto:Naz@lkkauto.com) | Fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)  
**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.