From: Date: 3/6/2021	Veh No: SLU2204M Yr Regn: 11/3 /2009
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TO I WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLUDDO4M	Make: Mazda 2 c.c 1498
at Workshop m/s Dean Autopro	Colour Grey A/C: Insured / Std / NI / NA
of 160 Sin MingDr # 01-14	Sp.Reading 207690 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: ZY5/8581
Policy No.	C/No: UMODE104190130144.
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Iporder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: morder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / STRim / STD A/Rim or
	Tyre Size: F: 185/60/15 Firenza
(Policy Condition)	R: 195/55/15 Kaspen
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 16,000	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm , R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: 5 days Res.: Yes or No	D.O.A. 19/5/2021 D.O.I. 3/6/2021
Lum Sum: % 3 Val.: Yes or No	Survey held at Pean Astopro
CA / REV / REP. / 24 HRS W.P	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/OUT	ff and due to collicion
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Recommended coris L/S	43650/2 TOPEN 1111 14/6/2021
- TOWNSONGER SERVIS 21.	1
m V 16,000/2	Talin
PV 6,985/Y	146/201
NV 9,015 ×	· · · · · · · · · · · · · · · · · · ·
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation: Site Insp. (\$)S+RSSI
Add Fe	or and map
	: Interview (\$) Photos
Repressionat:	:Tech. Invs (\$) Others
Lump Sum/I.B.I: (5	: Weellend (\$)
	TOTAL

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com /teamautopl@gmail.com

SJE :				Vehicle Nos :	SLU 2204 M
	f Survey :		Model:	Mazda 2	
	f ReSurvey: After-F		Year:		
Contac	its:			Chassis No:	
* AGR	EED Cost Of Repair and Repair Day/s w	ith SIF *			
Amou		TEN SIZE			
A.IIIOUI				Working Day:	
Nos.	PARTS			Sylvania de la companya de la compan	2000
1	Tailgate		Qty	Unit S\$	TOTAL S\$
2	Tailgate logo		1	\$ 1,358.00	\$ 1099.60 1,358.00
3	Tailgate logo Tailgate emblem 'Mazda 2'		1	\$ 88.20	\$ 48,50 -88.20
4			1	\$ 68.90	\$ 35 , 24 68.90
5	Tailgate inner lock		1	\$ 219.80	\$ 219.80
6	Tailgate inner lock striker		1	\$ 68.10	\$ 68.10
A STATE OF THE STA	Tailgate inner trim board	1	\$ 355.90	\$ 255.90	
7	Tailgate weatherstrip		1	\$ 189.60	\$ 189.60
8	Tailgate antenna sensor		1	\$ 358.60	\$ 358.60
9	Tailgate windscreen moulding		1	\$ 157.50	\$ 68.20 157.50
10	Rear bumper	The state of the s	1		\$ 650.60 -1,096.70
11	Rear bumper side retainer		2	\$ 37.60 105.00	
12	Rear bumper reinforcement	THE RESIDENCE OF STREET	1	\$ 684.20	\$ 684.20
13	Rear bumper number plate lamp	2	\$ 84.00	\$ 168.00	
14	Rear end panel	1	\$ 830.40	\$ 830.40	
15	Rear end panel top garnish	1	\$ 109.40	\$ 85.00 109.40	
16	Taillamp	2	\$ 465.40 609.50	\$ 930.80 1,219.00	
17	Taillamp lower bracket		2	\$ 62.80	\$ 125.60
	0 -	2992.30		Parts Sub Total :	\$ 7,307.90
	@ 20%	598.46	20%	Discount :	\$ 1,461.58
		2393.84		PARTS TOTAL :	\$ 5,846.32

Nos.	SPECIAL NETT	Qty		Unit S\$	TOTAL	S\$
1	Sundries	1	\$	80.00	\$	80.00
2	Tailgate sealant	1	\$	100.00	\$	100.00
3	Tailgate inner trim board clips	1	\$	50.00	\$30.00	50.00
4	Tailgate windscreen sealant	1	\$	100.00	\$40.00	100.00
5	Tailgate windscreen inner seal	1	\$	60.00	\$	60.00
6	Tailgate windscreen prime & cleaner	1	\$	80.00	\$	20.00
7	Rear bumper clips	1	\$	50.00	\$30.00	50.00
8	Rear bumper reverse sensor	2	\$	250.00	\$200.00	500.00
9	Rear end panel sealant	1	\$	100.00	\$40.00	100.00
10	Rear end panel top garnish clips	1	\$	50.00	\$30-00	50:00
11	Taillamp seal	2	\$	√60.00	\$ ~	120.00
12	Taillamp clips	2	\$	50.00	\$	100.00
13	Rear number plate w/casing	1	\$	80.00	\$ 50.00	80.00
13	Rear number plate w/casing	1	PECIA	L NETT TOTAL :	\$ 50.00	į

Nos.	LABOUR	S\$
1	R&R tailgate component NN	
2	R&R tailgate windscreen	\$ 30.00
3	R&R rear bumper reverse sensor	\$120-00 250.00
4	Upholstery	\$ 200.00
5	Check wiring	
6	Panel beating	
7	Rust proofing	\$ 800.031,200.00
8	spray painting	\$ 200.00
	LABOUR TOTAL :	\$ 600.001,200.00

Survey Resurvey
3/6/2021
TOTIM Thim
thin
thin
1300hrs
1600hrs

Lump sum repair

Repair days 5

1610.00

PARTS TOTAL : \$ 5,846.32 SPECIAL NETT TOTAL : \$ 1,470.00

LABOUR TOTAL : \$ 3,400.00

GRAND TOTAL: \$ 10,716.32

Parts 2,393.84
SN 540.00
Labour 1,610.00

4543.84

@ 20% 908.77
3635.07

45 3,650/2

TOTIM Min 14/6/2021

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third ; arty survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

MOTORCAR (Rear)

÷.

(1)Replace (1) (2)Repair() (3)Check ()
(4)Not Constituent (10)

Missing	(13)Tom	(14)Unconfirmed	(15)Not Working	
ar Par	win.			

Personal P	rtlon				
	THE RESERVE AND ADDRESS.	Item	CON	AC	Qty
		Rear Number Plate	BT	/	
1138	993627	Rear Number Plate Base			
		Rear Number Plate Garnish	BT.		
1140	993632	Reaf Number Plate Lamp		1	
1141	992958	Rear Bumper	BR	V	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket	1	-	
1148	993068	Rear Bumper Side Retainer	NEC	1	2
1149	993045	Rear Bumper Reinforcement	Nec		
1150	992970	Rear Bumper Beam	1	-	
1151	993077	Rear Bumper Sponge	-	1	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	1	1	
1156	993044	Rear Bumper Reflector		T	
1157	993023	Rear Bumper Lower Spoiler	1	1	1
1158	994023	Reverse Sensor	SC	V	2.
1159		Rear End Panel			
1160	993339	Rear End Panel Top Garnish	BR	1	
1161		Rear End Panel Inner Trim	-	_	-
1162		Boot Compartment Inner Trim	-	-	-
1163	993851	Rear LH Taillamp	BR	V	-
1165	993853	Rear LH Taillamp Gamish	-	-	-
		Rear LH Taillamp Panel Rear RH Taillamp	100	1-	-
1167	00775	Rear-RH Taillamp Garnish	BR	V	-
1168	007850	Rear RH Taillamp Panel	-	+-	1-
1169	003554	Rear Apron Panel	-	+-	-
1170	997894	Bootlid	-	+	-
		Bootlid Emblem	-	+	-
1172		Bootlid Handle	-	+	-
1173		Bootlid Moulding	-	+	+-
1174		Bootlid Reflector	-	+	-
1175		Bootlid Lamp LH	-	-	-
-1176	992899	Bootlid Lump RH	-	-	1
1177	99524	Bootlid Lock	1.	1	1
1178	99037	Bootlid Rubber	1	1	1
1179		Bootlid Hinge		1,	
1180	99387	Bootlid Spoiler	,		1
1181		Tailgate	DD	V	
1182		Tailgate Emblem	NE		12
1183		Tailgate Outer Handle	160		
1184	994640	Tailgate Moulding			
1185	99454	Tailgate Garnish			-
1186	994648	Tailgate Reflector /			
1187		Tailgate Lamp		1	-
1188	99464	Tailgate Protector		-	-
1189		Tailgate Wiper Arm	-		
1190		Tailgate Wiper Blade	-		-
1191	-	Tailgate Wiper Nozzle		-	-
1192		Tailgate Wiper Motor		-	-
1193	99460	2 Tailgate Glass.			
1194		7 Tailgate Glass Rubber			
1195		Tailgate Glass Moulding	NE	CI	/
1196	99460	7 Tailgate Glass Sealant			
1197	00462	7 Tuilgate Class Courant	-	-	
		I Tailgate Rubber		1	
		1 1 4115,010 1100001		-	
1198					
	99461	Tailgate Hinge Tailgate Damper	-	-	-

		Vehilcle Noi . SLU			
NAC	INC	Item	CON	AC	Qt
1202	.993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			_
1204	995065	Spare Tyre			_
	994326	Spare Tyre Lock Screw		-	-
1206	993787	Spare Tyre Cover		_	-
1207	995323	Triangle Breakdown Sign			-
1208		CD Changer Assy		_	-
1209		Antenna		_	_
1210	990534	Centre Exhaust Pipe Assy -			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			_
1213	993357	Rear Exhaust Chrome Pipe		_	_
1214	993361	Rear Exhaust Mounting		_	-
1215		Rear Exhaust Heat Shield		-	-
1216	995223	Rear LH Chassis Member	-	-	-
1217		Rear RH Chassis Member	-	-	-
1218	993436	Rear LH Fender	-	-	-
1219	993449	Rear LH Fender Protector	-	-	-
1220	993420	Rear LH Fender Inner Panel	-	+	-
1221	993431	Rear LH Fender Inner Trim	-	+	-
1222	993415	Renr LH Fender Inner Garnish Renr LH Fender Inner Shield	-	1-	-
1223	993425	Rear LH Mudflap	1	1	-
1225	003033	Rear LH Wheel Rim	1	1	-
1226	994025	Rear LH Rim Cover		1	1
1227		Rear-LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector		_	-
1230	993420	Rear RH Fender Inner Panel '	-	-	-
1231	993431	Rear RH Fender Inner Trim	-	1	1-
	993415	Rear RH Fender Inner Garnish	-	-	-
1233	993425	Rear RH Fender Inner Shield	-	+	-
1234	993622	Rear RH Mudflap	-	+	+-
_		Rear RH Wheel Rim Rear RH Rim Cover	-	+	+
1236		Rear RH Tyre	-	+	1 4
		Rear Fender Extension Panel LH		1	1
1230	003401	Rear Fender Extension Panel RH	1	+	1
1230	003430	Rear Fender Inner Top Gamish	1	1	1
1241	993673	Rear Pender 1/4 Glass .			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant	-	-	1 3
1244	993949	Renr Windscreen Glass	-	-	1
1245	993976	Rear Windscreen Rubber	-	+	3
1246	993961	Rear Windscreen Moulding	-	+	- 100
1247	993955	Rear Windscreen Sealant	-	-	183
1248	994729	Third Brake Light Rear Fender Air Grille	-	+	-24 -24
1249	993383	Fuel Lid	1	-	198
1250		B Fuel Neck	-	1	397
1251	992170	Fuel Tank	1	1	33
1253	99218	Fuel Tank Bracket	1	1	一流
1254	99219	Fuel Tank Float			196
图60%		7 Sticker			138
TAMES			_	1	100
-					28
-					The state of
-					
-	-				100
-				T	1
	-				1000
-					100
-					139
-					1
					十三
					100

No of liems: 1

Assessor: T.Glim Alm 13/6/2021



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/05/2021 12:07 (SGT) Date of Accident 19/05/2021 15:30 (SGT) Exact Location of Accident Ubi Ave 1, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU2204M

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Fultonn Motor Pte Ltd Company Reg No 2XXXXX673R Email Address fultonnmotor@gmail.com Mobile Phone No (Phone) +65-91372386 Alternative Phone No (Home) +65-91372386

VEHICLE PARTICULARS


Manufacturer Mazda 2 Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party vour vehicle? Vehicle Category Commercial vehicle Transmission Auto 1499

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd Type of Coverage **ThirdParty** Fleet Policy Policy Number 5114402779-01-000004 Cover Note Number

DRIVER

Chow Yinghao Benjamin SXXXX725E



Date Of Birth 26/09/1983 Occupation Outdoor Date Of Driving Pass 17/06/2004 Driving experience 16 YEARS AND 11 MONTHS Gender Mobile Number (Phone) +65-91372386 Alt. Phone Number Email Address fultonnmotor@gmail.com Address 160 Sin Ming Drive #08-04 Sin Ming Autocity Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? **DETAILS OF POLICE ACTION**

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJL5133K

Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category Private car

Name of Driver
Contact Number
Address
Address complement -

Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

on +	he s	rand	due	mind	ti	me :	VU	ricle ~	A' ha	Hav	lly	aten	
To the				Glas		A. (a	A V	Thu .	co E E c	lym	Luga	120	00
7 desig) merce		W.C	u lan		8/19/16		1116				1000	4.500
Inh				The Control of									
													mared
forward	. 1	Was	Still	Statio	Nory	when	c	Buld	enly 4	भर ८	2 V	vje.	empart
nittig	me	en.	the	(tu	et	7	ven	ile.	1)°	4 do	· · ·	to 1	enimo
they (unici	-B'	n/	>	(cl)	1918	VIY	c m	e. Th	4 15	oy!		
7.000													
		A SECTION											
											10.000		
													No. of the last
					ALLEA M								
					92.75								
V100 6							ap av	90780 NO			no tel		
		V = 1							35分别。 35分别。第	(地方) (水)			
	. = 1.6	William of											
Samuel .											WE'S		
		NEW T											
Declarat	llan.												
We decla		egoing D	articulars	are true i	n every	respect							
VWe decia	re the roi	C'S Dire											1
1		NA NA		S	-ei	7 :							
Policyhold	er's Signi	iture / Da	te &	Driver's 8	Signatur	e (# drive	is not th	e policyho	lder) / Date		onnel	Report	ng Centre
400000							(55) E 30 E						THE RECEIVE OF

The integ

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process,
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful insrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the making of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Driver's Signature (y driver is not the policyholder) / Date Policyholder's Signature / Date & & Time

Witnessed by Reporting Centre

Sketch Plan



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	
Owner ID:	Company
Vehicle Details	673R
Vehicle No.:	SLU2204M
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2021
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 AT R
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	ZY518581
Chassis No.:	JM0DE10Y190130144
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$16,304.00
Original Registration Date:	11 Mar 2009
First Registration Date:	11 Mar 2009
Transfer Count:	4
Actual ARF Paid: Intended PARF Rebate Details	\$16,304.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	10 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$6,985.00
Total Rebate Amount: Message	\$6,985.00
Please note that the 5-year COE for this vehicle cannot be fuvehicle reaches its statutory lifespan (if applicable), whicheve	urther renewed. The vehicle must be de-registered upon COE expiry or when the er is earlier.

The information contained herein is correct as at 14 Jun 2021

OK

MV 16000 7 PV 6,985 7 NV 3,015 7

Tain Mui 14/6/2021

SGCARMART.COM

Login Sign up

New Cars

Post an Ad

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources




Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

Ways of Selling

Advertiser Login

Only 2mth Old = As New Car, 3 Year Warranty & 5 Years Free Servicing By Wearnes, HTS Motor StarAd

Lake View **※ Credit Pte Ltd** > Low prices guaranteed > Specialist in Japanese cars > Easy loan approval > All terms are negotiable



Well Maintained, No Repairs Needed. Accident Free. Welcome Any 3rd Party Workshop Inspection. Trade In Your Car Are Welcome. Bank & In House Loan Available. Insurance Are Available Too. Viewing By Appointment Only.

Posted: 14-Jun-2021 Tags: 2009 Mazda 2, Mazda 2, Mazda, 2



Mazda 5 2.0A (COE till 10/2023)

\$19,800

\$8,320 /vr

24-Nov-2008

1,999 cc 150,000 km

MPV

Available

Cheapest In Market, Beautiful Midnight Blue In Colour, Excellent MPV For Daily Usage! 100% Loan Available With Hassle-Free Loan Extremely Well Kept From Inside Out! Trade In Welcome! Flexible Bank/In House Financing Available With Fast And Easy Loan Appro...

Posted: 31-May-2021 Tags: 2008 Mazda 5, Mazda 5, Mazda 5



Mazda 2 HB 1.5A R (COE till 09/2028)

\$57,000

\$7,850 /yr

18-Sep-2008

1.498 cc

Hatchback

Available

Engine Overhauled, Gearbox Overhauled With Clutch Replacement, Battery Changed, Front Axle Replaced, Fully Refurbished Aircon And Compressor, Refurbished Interior With New Steering Wheel, Roof Lining Maintained And New Car Spray Paint! All Wear And Te...

Posted: 27-May-2021 Tags: 2008 Mazda 2, Mazda 2, Mazda 2



Mazda 2 HB 1.5A R (COE till 09/2028)

18-Sep-2008

1.498 cc

Hatchback

SOLD

Just Arrived! Well Maintained By Previous Owner! Loan With High Trade In Available, Price Negotiable, Call Now Or Visit Our Showroom

Posted: 04-May-2021 Tags: 2008 Mazda 2, Mazda 2, Mazda, 2



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Mazda 5 2.0A (COE till 09/2028)

\$49,999

\$6,890 /yr

15-Sep-2008

1,999 cc

MPV

Available

Posted: 27-May-2021 Tags: 2008 Mazda 5, Mazda 5, Mazda, 5

DIRECT OWNER



Mazda 2 HB 1.5A R (COE till 09/2023)

N.A

04-Sep-2008

1,498 cc

Hatchback

SOLD

Well Kept, Rare In The Market, Road Tax Till Sep 2021, Accident Free, Best Transport, Low Maintenance And Low Fuel Consumption, Bank And In House Loan Available, Immediate Approval.

Posted: 21-May-2021 Tags: 2008 Mazda 2, Mazda 2, Mazda, 2

Mazda MX-5 Roadster 2.0M (COE till 08/2028)

\$90,800

\$12,660 /yr

14-Aug-2008

1.998 cc

170,000 km

Sports

Available DIRECT OWNER

Rare Manual Transmission + Hard Top Combi. Family's 4th Car, Female Enthusiast's Weekend Drive. Done Up For Road Use With Over