



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC21000513/Gqf3e2-1	
			Date: 14/06/2021	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SLA 4148J	Veh. Inspected	SJT 1365S
	Policy No.		Coverage (\$)	0.00
	Claim No.	20/21/21/VP05/024115	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	04/06/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA VIOS	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053HY9305131182	Colour	BLUE
	Odometer	230662 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/45Z R16	TOURADOR	6 mm
	L/H Front Tyre	205/45Z R16	TOURADOR	6 mm
	R/H Rear Tyre	205/45Z R16	TOURADOR	6 mm
	L/H Rear Tyre	205/45Z R16	TOURADOR	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	09/01/2021	Inspection Date	12/01/2021
	Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	