

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 7 June 2021 12:17 pm
To: tlauto
Cc: SUR
Subject: AIG-OD SMZ 3347P DOA: 11/05/2021

Dear Candy,

As instructed by our client, please proceed to repair the insured vehicle **SMZ 3347P (Excess \$1,700/-)**.

Please take note the FRONT FENDER – LH to repair.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey of before paint for all panels and parts.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)