

TAX INVOICE

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
 Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
 Email: info@minghee.com (Main), account@minghee.com (Accounts)
 Website: http://www.minghee.com

GST REG.NO.: M2-0090482-6 CO REG.NO.: 198905613E

ACCOUNT NUMBER : TONGLUC1 TIME:14:45
 TONG LUCK AUTO PTE LTD
 160,SIN MING DRIVE #07-01
 SIN MING AUTOCITY
 SINGAPORE 575722

Telephone No: 62500088

ROUTE
 SMI

DELIVER TO :
 TONG LUCK AUTO PTE LTD
 160,SIN MING DRIVE #07-01
 SIN MING AUTOCITY
 SINGAPORE 575722

INVOICE NO. 8221683

DATE	10/06/2021	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SMZ3347P	OUR REF.	17695

PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA205 690 33 01	WHEEL HOUSE	3A-2C	1 PC	98.00	98.00
2 MBA205 820 01 61	HEADLAMP UNIT	6B-3B	1 PC	1,850.00	1,850.00
3 MBA205 880 01 40 9999	TRIM BUMPER	4B-1AA	1 PC	1,080.00	1,080.00
4 MBA205 620 34 01	BRACKET	1E-7C	1 PC	68.00	68.00
5 MBA000 905 55 04	DISTANCE SENSOR	1E-9C	1 PC	138.00	138.00
6 MBA000 542 12 51	DECOUPLING RING	1A-01F	6 PCS	8.00	48.00
7 MBA205 880 01 06	FENDER	3C-1B	1 PC	590.00	590.00
8 MBA205 885 08 21	MOUNTING RAIL	1A-7J	1 PC	38.00	38.00

TOTAL	SIN	3,910.00
ADD GST	7%	273.70
AMOUNT DUE	SIN	4,183.70

Payment via telegraphic transfer to
 Name of Bank: United Overseas Bank
 Account Name: Min Ghee Auto Pte Ltd
 Branch Code: 046
 Account No.: 503-309-511-3
 *Please send a screenshot of your payment/transfer confirmation to account@minghee.com.



SIGN & COMPANY'S STAMP

DATE
 ALL CHEQUES MUST BE MADE PAYABLE TO
 MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
Sin Ming Autocare Singapore 575721
Tel No. 6452 6657 Fax No. 6451 4618
Email : autosoon1@gmail.com
UEN: 200709808N GST Reg No: 200709808N

Tax Invoice No: DL 717128
PO Number:
Date: June, 16 2021
Car Plate No: SMZ3347P
Mercedes Benz C180
Chassis: WDD2050402R326808
Remark: Notes
Mileage: km

TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01 SIN MING AUTOCITY SINGAPORE 575722
PHONE: 6250 0088 FAX: 6250 5545

S.No	Quantity	Particular	Unit Price	Amount (SGD)
1	1	To reset and reprogram headlamp fault code	180.00	180.00

Sub Total	180.00
GST 7%	12.60
Total	192.60
Paid Amount	0.00
Total Due	192.60

Terms of Payment: Cash

Customer's Signature/Co. Stamp

I/We agree to pay all work and parts required for the repairs described above at your retail charge. All goods shall remain the property of the seller until paid for in full. I have read and accept your terms and conditions.

For AutoSoon Pte Ltd