

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
B
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLX3767H*
at Workshop m/s: *fl.*
of: _____
Insured: *SDP250M*

Policy No. _____
Claims No. **C10010441/HA**


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *\$666k.*

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: *6* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LYA 47906

Vehicle: IN / OUT

Date: _____ Person Contacted: *Dez 13*

Date / Time Action / Instruction *not 16094*
7:13pm 2126.40

14/6/21 4/5 \$7500 confirmed with Alar. (Red \$21290.80, 74%)

Veh No: *SLX3767H* Yr Regn: *09/07/15*
Type: *B* M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *49/*

Make: *Toyota harrier* c.c. *1986*

Colour: *Green / Gold* A/C: Insured / Std / NI / NA

Sp. Reading: *78926* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *25460 00 23981*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *B* In order / Jammed / Leaked / Burnt or

Brake: *B* In order / Jammed / Leaked / Burnt or

Modi: *B* Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: *235/55 R19*

B BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *4/6/21* D.O.I. *4/6/21*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

16/06 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format: TP

Lump Sum *H.D.* \$ 7500

TOTAL

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

Submit to insurance. Not followed

4/6/21
2/5 \$7500 6 days.

VEHICLE No :SLX 3767H

1PC	REAR WINDSCREEN		111	\$1,488.10	X
1PC	REAR WINDSCREEN MOULDING	113.10	ner	\$188.20	✓
1PC	TAILGATE		Worped / sent	\$1,866.10	✓
1PC	TAILGATE OUTER GARNISH		111	\$981.00	X
1PC	TAILGATE REAR LOGO		ner	\$85.00	✓
2PCS	TAILGATE REFLECTORS @\$785.10		111	\$1,570.20	X
1PC	TAILGATE 'WALD' EMBLEM		ner	\$80.00	✓
1PC	TAILGATE 'BLACK BISON' EMBLEM		ner	\$105.00	✓
1PC	TAILGATE INNER LOCK	459.10	shuck	\$499.20	✓
1PC	TAILGATE INNER TRIM		111	\$699.10	X
1SET	TAILGATE INNER TRIM CLIPS		111	\$50.00	X
2PCS	TAILGATE DAMPERS @\$455.00		111	\$910.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$125.00	88.10	2/5 cne	\$250.00	1PC
2PCS	REAR BUMPER PDC SENSORS @313.00		111	\$626.00	2005/21
1PC	REAR ANTENNA SENSOR		111	\$488.10	X
1PC	REAR END PANEL	803.10	body p2	\$831.00	✓
1PC	REAR END PANEL TOP GARNISH	360.89	111	\$540.50	✓
1PC	REAR FLOOR PANEL		111	\$1,166.00	X
1PC	REAR FLOOR PANEL TOP BOARD		111	\$988.10	X
2PCS	REAR FENDERS @\$1245.00		111	\$2,490.00	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$799.10	725.10	0/5 ref to n	\$1,598.20	1PC
1PC	REAR AIR VENT N/S		111	\$88.90	X
2PCS	TAILLAMPs @\$1045.00	810.00	0/5 cne	\$2,090.00	1PC
1PC	TAILGATE WEATHERSTRIP	444.4	111	\$412.10	✓
				\$20,090.80	

(252)

S.NETT

1SET	REAR BUMPER SPORT ASSY	To n	\$2,800.00	1800
1SET	REAR BUMPER REFLECTOR LED	cne	\$300.00	250
1SET	REAR BUMPER CLIPS	ner	\$50.00	✓
1PC	REAR BUMPER CENTRE THIRD BRAKE LIGHT	cna	\$250.00	✓
1PC	REAR WINDSCREEN SEALANT	ner	\$50.00	40
1PC	REAR END PANEL SEALANT	ner	\$50.00	✓
1SET	REAR REVERSE CAMERA	111	\$450.00	X

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACING REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO TRANSFER TAILGATE COMPONENTS	\$120.00	60
TO SPRAY RUST PROOFING	\$150.00	60
TO MOUNT VEHICLE ON CAR O-LINER	\$380.00	X

LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING [MULTI COLOUR]

\$1,800.00 800
\$1,800.00 1300
TOTAL \$28,790.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5547.59
25-
P-4460.69
S-12440
L-2490