

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21006422/R1GS3Q2
Date: 15/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MCV0001295_01
Claimant Vehicle No :	SJL294L	Insured Vehicle No :	GBE8187S
Date of Loss:	30/05/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0002402

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL294L		
Make & Model:	HONDA CROSSROAD, 1.8 (A)	Engine No:	R18A3011467
Reg. Date:	12/11/2008 (Man. Year: 2008)	Chassis No:	RT11008436
Colour:	Black	Odometer:	274394 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R15	Rear Tyre Size:	215/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,913.00	1,404.00	2,509.00	64.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	600.00	880.00	59.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,393.00	2,004.00	3,389.00	62.84
Approved Total (Overridden) (S\$)		1,600.00		

(S\$)	5,393.00	1,600.00	3,793.00	70.33
+ GST 7.00/7.00% (S\$)	377.51	112.00	265.51	70.33
Nett Amount (S\$)	5,770.51	1,712.00	4,058.51	70.33
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,959.45		

INSPECTION

Date of Assignment: 04/06/2021

Date Inspected: 08/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Hin Lung Workshop (HQ)
Blk 1008 Bukit Merah Lane 3, #01-20
Singapore 159722

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2021)
Parts:	M1-SUV	HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL294L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,800.00 F	*1,200.00 FL
2	1		*FRONT SIDE RETAINER LEFT	Serviceable	84.00 F	*- FL
3	1		*FRONT SIDE RETAINER RIGHT	Serviceable	84.00 F	*- FL
4	1		*FACE ,RIGHT BUMPER SIDE	Scratched	160.00 F	*160.00 FL
5	10		*BUMPER CLIPS	Necessary	55.00 F	*55.00 FL
6	1		*BUMPER UNDERCOVERAGE	Serviceable	320.00 F	*- FL
7	1		*FRONT FENDER WHEEL ARCH	Scratched	410.00 F	*340.00 FL
					Sub Total (\$\$)	1,755.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	351.00
					Total Parts (\$\$)	1,404.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE NEW PARTS ,REMOVE/REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR	New	500.00	400.00
2	SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT	New	900.00	200.00
3	CHECK WIRING AND PROPER FUNCTIONING	New	80.00	0.00
Gross Labour Cost (\$\$)			1,480.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >